

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2776X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RH DOOR OUTER HANDLE	GRAZED	276.00	245.30
1	FRONT RH DOOR OUTER PROTECTOR	GRAZED	320.00	288.00
1	FRONT RH DOOR OUTER GLASS WEATHERSTRIP	SERVICEABLE	385.40	-
1	REAR RH SLIDING DOOR ASSY	DENTED / BENT	2,159.20	1,665.32
1	REAR RH SLIDING DOOR PROTECTOR	GRAZED	207.80	207.80
1	REAR RH SLIDING DOOR HANDLE	GRAZED	276.00	245.30
	LESS 10% DISCOUNT		-	-265.17
			3,624.40	2,386.55
	SPECIAL NETT ITEMS			
1	REAR RH SLIDING DOOR "BLACK" STICKER (SN)	NECESSARY	180.00	60.00
1	REAR RH SLIDING DOOR GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR RH "CORPORATE" ADVERTISEMENT & ARTWORK (SN)	NECESSARY	200.00	80.00
			460.00	180.00
	<u>LABOUR</u>			
	REMOVE & REINSTALL SLIDING DOOR GLASS TO FACILITATE REPAIRS.		120.00	80.00
	LABOR FOR REMOVE AND REFIX SLIDING DOOR COMPONENTS AND MECHANISMS.		120.00	50.00
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	400.00
	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		60.00	30.00
			1,500.00	860.00
	GRAND TOTAL		5,584.40	3,426.55



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AIS22004107/Uqy3n2

CHUA KANG SENG

**Licensed Appraiser**