



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBQ 3171G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	N/S BRAKE LEVEL PEDAL	SERVICEABLE	70.00	-
2	SIGNAL LAMP @\$55.00	SERVICEABLE	110.00	-
2	SIGNAL LAMP COVER (BLACK) @\$65.00	MTG CRACKED	130.00	130.00
2	SIGNAL LAMP COVER (YELLOW) @\$85.00	CRACKED	170.00	170.00
1	FRONT WINDSHIELD	SERVICEABLE	95.00	-
2	FRONT FAIRING @\$268.00	BROKEN	536.00	420.00
1	FRONT FORK COVER	MISSING	66.00	66.00
1	HEAD LAMP	BROKEN	680.00	680.00
2	HEAD LAMP FAIRING @\$225.00	CRACKED / MISSING	450.00	300.00
2	HEAD LAMP COVER @\$95.00	MTG CRACKED	190.00	190.00
1	FRONT MUD GUARD	BUCKLED	60.00	60.00
2	SIDE FAIRING @\$170.00	CRACKED	340.00	340.00
2	STEERING CONE @\$35.00	NECESSARY	70.00	70.00
2	STEERING STEM @\$140.00	BENT	280.00	280.00
2	HANDLE BAR @\$65.00	BENT (1PC ONLY)	130.00	65.00
2	HANDLE BALANCER @\$18.00	N/S MISSING	36.00	18.00
2	FRONT FORK @\$133.00	REPEATED	266.00	-
2	FRONT FORK INNER TUBE @\$56.00	BENT	112.00	112.00
2	REAR FAIRING @\$155.00	SERVICEABLE	310.00	-
1	METER ASSY	SERVICEABLE	135.00	-
1	REAR AIR CLEANER BOX ASSY	SERVICEABLE	580.00	-
1	REAR AIR CLEANER BOX BOTTOM COVER	CRACKED	380.00	380.00
1	REAR COVER (BLACK)	SERVICEABLE	155.00	-
1	REAR COVER (YELLOW)	SERVICEABLE	190.00	-
1	CENTRE CONSOLE BOX	DISTORTED	115.00	115.00
1	N/S CENTRE CONSOLE BOX COVER	CRACKED	210.00	210.00
1	O/S CENTRE CONSOLE BOX COVER	MTG CRACKED	220.00	220.00
2	FRONT STEP PANEL @\$225.00	N/S CRACKED / O/S SERVICEABLE	450.00	225.00
2	FRONT STEP PANEL GARNISH @\$175.00	N/S CUT / O/S SERVICEABLE	350.00	175.00

Report Ref No. CS/SMR22004111/Kny3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT & REAR SPORT RIM @\$236.00	SERVICEABLE	472.00	-
1	SWING ARM	SERVICEABLE	315.00	-
1	CENTRE STAND	TO REPAIR SEE LABOUR	180.00	-
1	SIDE STAND	TO REPAIR SEE LABOUR	160.00	-
	LESS 10% DISCOUNT		-801.30	-422.60
			7,211.70	3,803.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NO PLATE (SN)	SERVICEABLE	50.00	-
1	EXHAUST SIDE COVER (SN)	SERVICEABLE	120.00	-
			170.00	-
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF CENTRE STAND AND SIDE STAND.		800.00	180.00
	TO PUTTY AND SPRAY PAINTING.	NOT NECESSARY	500.00	-
	TO CHECK WIRING.		150.00	15.00
	TO CHECK CHASSIS ALIGNMENT.		420.00	120.00
			1,870.00	315.00
<b>GRAND TOTAL</b>			<b>9,251.70</b>	<b>4,118.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,250.00</b>

Report Ref No. CS/SMR22004111/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.