



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 7470B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	NOT NECESSARY	1,985.00	-
1	FRONT FENDER RH (CONSISTENT)	DENTED / BENT	987.00	905.00
1	FRONT FENDER COWLING RH (CONSISTENT)	NOT NECESSARY	321.20	-
1	FRONT FENDER EMBLEM HYBRID RH (CONSISTENT)	NECESSARY	96.00	96.00
1	SIDE MIRROR RH (CONSISTENT)	BROKEN	698.00	698.00
1	FRONT DOOR RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,875.00	-
1	FRONT DOOR WEATHERSTRIP RH (CONSISTENT)	NOT NECESSARY	218.00	-
2	FRONT DOOR HINGE RH @\$65.00(CONSISTENT)	NOT NECESSARY	130.00	-
1	FRONT KNUCKLE ARM RH (CONSISTENT)	NOT NECESSARY	874.00	-
1	FRONT KNUCKLE ARM BEARING RH (CONSISTENT)	NOT NECESSARY	215.00	-
	LESS 25% DISCOUNT		-1,849.80	-424.75
			5,549.40	1,274.25
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER CLIPS (SN)(CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT SPORTS RIM RH (CUT) (SN)	NOT CONSISTENT WITH THE IMPACT	800.00	-
1	SET FRONT FENDER COWLING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	FRONT FENDER SEALANT (SN)(CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
			1,110.00	-
<u>LABOUR</u>				
	TO CHECK ELECTRICAL WIRING.		200.00	20.00
	TO CONDUCT WHEEL ALIGNMENT CHECK .	NOT NECESSARY	150.00	-
	REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	300.00	-
	CHECK AND RESET FAULT CODE LIGHT ON .	NOT NECESSARY	300.00	-
	APPLY ANTI RUST ON AFFECTED AREAS .		100.00	30.00
	SPRAY PAINTING ON AFFECTED AREAS .		800.00	520.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRONT DOOR RH.		800.00	300.00
			2,650.00	870.00
GRAND TOTAL			9,309.40	2,144.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC4/ASM22004121/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.