

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22004131/KQCN2**Date:** 03/06/2022**REFERENCE**

Insured/Claimant: BIS MOTORING PTE LTD Policy No: MCF22A00000100
Date of Loss: 27/04/2022 Nature of Claim: OD Claim No: DMCF2200031H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX4966T**
Make & Model: KIA CARENS, 1.7 D DCT 5DR FWD (A) Engine No: D4FDJH551006
Reg. Date: 29/03/2018 (Man. Year: 2018) Chassis No: KNAHU815VJ7203852
Colour: Metallic Light Brown Odometer: 330936 km
Engine Capacity: 1685 cc
Market Value/New Car Price: S\$73,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Grenlander 8 mm Rear Left Side: DURATURN 9 mm
Front Right Side: Grenlander 8 mm Rear Right Side: DURATURN 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,978.70	3,665.20	313.50	7.88
Miscellaneous Items	145.00	25.00	120.00	82.76
Labour	2,670.00	1,860.00	810.00	30.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,793.70	5,550.20	1,243.50	18.30
Approved Total (Overridden) (S\$)		5,200.00		
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	4,793.70	3,200.00	1,593.70	33.25
+ GST 7.00/7.00% (S\$)	335.56	224.00	111.56	33.25
Nett Amount (S\$)	5,129.26	3,424.00	1,705.26	33.25

INSPECTION

Date of Assignment: 04/05/2022 Present Location: Munich Autocare Pte Ltd (HQ)
Date Inspected: 05/05/2022 Inspected At: Munich Autocare Pte Ltd (HQ)
Estimated Period of Repair: 6.0 days 60 Jalan Lam Huat, #07-43
Singapore 737869

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2022)
Parts:	M1-MPV	KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX4966T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL LAMP LH (WCP)	Broken	114.00 F	*114.00 F
2	1		*REAR TAIL GATE LAMP LH (WCP)	Mtg Cracked	180.00 F	*180.00 F
3	1		*REAR FENDER LH (WCP)	Bent	720.00 F	*720.00 F
4	1		*REAR OUTER GLASS LH (WCP)	Serviceable	216.00 F	*- F
5	1		*REAR BUMPER (WCP)	Mtg Cracked	264.00 F	*264.00 F
6	1		*REAR BUMPER SIDE BRACKET LH (WCP)	Cracked	18.00 F	*18.00 F
7	1		*REAR DOOR LH (WCP)	Bent	576.00 F	*576.00 F
8	1		*REAR RIMS R16 (WCP)	Dented	360.00 F	*360.00 F
9	1		*REAR AXLE WITH KNUCKLE ARM (WCP)	Bent	816.00 F	*816.00 F
10	1		*REAR ABSORBER LH (WCP)	Bent	138.00 F	*69.00 F
11	1		*REAR HEEL HUB (WCP)	Bent	168.00 F	*168.00 F
Supplementary #1						
12	1		*LID TANK (WCP)	Cracked	35.00 F	*35.00 F
13	1		*ABSORBER COVER (WCP)	Necessary	12.00 F	*12.00 F
F=Franchise part.						
Sub Total (\$\$)					3,617.00	3,332.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					361.70	333.20
Total Parts (\$\$)					3,978.70	3,665.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER CLIPS Necessary	25.00	25.00
2	1	REAR TYRE 205/55/R16	120.00	0.00
Sub Total (\$\$)			145.00	25.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING,REALIGN DISMANTLEREAR BUMPER, REAR BOOT LID, END PANEL OUTER, REAR TAILLAMP PANEL LH, REAR FENDER LH/INNER, REAR CHASSIS LH, REAR DOOR LH & ALL NECESSARY ETC	New	1,200.00	800.00
2	TO CHECK ELECTRICAL WIRING SYSTEM OF REAR SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF REAR TAIL GATE LAMP & TAIL LAMP LH/RH	New	120.00	20.00
3	TO DISMANTLE & RENEW REVERSE SENSOR	New	120.00	50.00
4	TO REMOVE & INSTALL LUGGAGE COMPARTMENT AND SIDE FENDER INNER TRIM TO ACILITATE REPAIR	New	120.00	100.00
5	TO PUTTY & SPRAY PAINT REAR BUMPER, REAR BOOT LID, END PANEL, REAR FENDER LH, REAR TAILLAMP PANEL LH, FENDER INNER LH, REAR DOOR CHASSIS LH/RH AND ALL NECESSARY ETC	New	600.00	600.00
6	TO REMOVE AND INSTALL REAR QUARTER GLASS LH INCLUDING TO CONDUCT WATERLEAK TEST	New	80.00	50.00
7	TO REPLACE REAR LEFT TYRE AND WHEEL RIM INCLUDING WHEEL BALANCING	New	80.00	20.00
8	T REMOVE AND INSTALL REAR SUSPENSION, REAR AXLE AND CONTROL SYSTEM TO FACLLIATE THE WORK	New	150.00	100.00
9	TO CONDUCT 4 WHEEL ALIGNMENT	New	80.00	60.00
10	TO REMOVE AND INSTALL FUEL TANK IN ORDER TO CARRY OUT REOAIR JOB INCLUDING TO CHECK FOR LEAK	New	120.00	60.00
Gross Labour Cost (\$\$)			2,670.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >