

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref	: CS3/ASM22004134/Vty3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	Dat	e: 02/06/2022	
	ATTN: CYNTHIA L	ОН	Cod	de: ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHB 2981A	Veh. Inspected	FBL 1872G	
	Policy No.	VFX/P2419140	Coverage (\$)	0.00	
	Claim No.	S2M03ZXL	Excess (\$)	0.00	
	Assign From	CYNTHIA LOH	Assign Date	05/05/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CBF190WH	c.c	184	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	LWBMC4692H1101896	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	140/70-17	PIRELLI	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	140/70-17	PIRELLI	6 mm	
	L/H Rear Tyre			mm	
4.	Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE O/	S AND N/S BODY.		
5.	5. General Information				
	Accident Date	29/04/2022	Inspect Date / Time	9 05/05/2022 ( 01:00 PM )	
	Survey held at	10 KAKI BUKIT ROAD 2 #01-36	S S(417868)		
	Repairer V MAPS MOTOR PTE LTD				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000				
5b. Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			

Report Ref No. CS3/ASM22004134/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser