

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22004137/Vncm4	
	300 BEACH ROAD #17-04/07 THE CO		Date:	31/08/2022		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBB 9008K	Veh. Inspected		FX 3022U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/22/22/VC05/025750	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		05/05/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HARLEY DAVIDSON XL1200C	c.c		1200	
	Engine No.	HIDDEN	Year of Reg.		2003	
	Chassis No.	5HD1CGP143K434764	Colour		BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/90-16	SHINKO		7 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	100/90-16	SHINKO		7 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS	ICLE SUSTAINED DAMAGES AT THE N/S BODY.				
5.	5. General Information					
	Accident Date	27/04/2022	Inspect Date / 1	Гime	05/05/2022 (02:30 PM)	
	Survey held at	EQBH PTE LTD				
		25 KAKI BUKIT ROAD 4 #03-46 SYNERGY @ KB SINGAPORE 417800				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC22004137/Vncm4

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser