

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 2696U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DROP SIDE GATE N/S (CONSISTENT)	TO REPAIR SEE LABOUR	2,201.00	-
1	DROP SIDE GATE LOWER MEMBER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	989.00	-
1	REAR MUDGUARD (FRT) N/S (CONSISTENT)	DISTORTED	266.00	266.00
1	REAR MUDGUARD (REAR) N/S (CONSISTENT)	DISTORTED	266.00	266.00
1	REAR MUDGUARD MUDFLAP N/S (CONSISTENT)	DISTORTED	145.00	145.00
1	REAR WHEEL HUB SHAFT N/S (CONSISTENT)	NOT NECESSARY	688.50	-
	LESS 10% DISCOUNT		-	-67.70
			4,555.50	609.30
	SPECIAL NETT ITEMS			
1	REAR STEEL RIM OUTER N/S (SN) (CONSISTENT)	сит	80.00	50.00
1	SET DROP SIDE GATE CORPORATE STICKER N/S (SN) (CONSISTENT)	NECESSARY	500.00	280.00
			580.00	330.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	TO CONDUCT WHEEL ALIGNMENT.		100.00	60.00
	TO DISMANTLE & REPLACED REAR WHEEL HUB N/S .	NOT NECESSARY	180.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF DROP SIDE GATE N/S AND DROP SIDE GATE LOWER MEMBER N/S .		900.00	400.00
	TO PUTTY & SPRAY PAINTING.		900.00	600.00
			2,210.00	1,080.00
	GRAND TOTAL		7,345.50	2,019.30

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22004148/Upa3q2

CHUA KANG SENG

Licensed Appraiser