

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004150/EVCQ2**Date:** 30/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00185202100

Claimant Vehicle No : GBH2168X **Insured Vehicle No :** SMK1108E

Date of Loss: 29/04/2022 Nature of Claim: TP Claim No: SNM22D203015/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH2168X**

Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A) Engine No: DFS084330

Reg. Date: 19/03/2018 (Man. Year: 2017) Chassis No: WV1ZZZ2KZHX157337

Colour: White Odometer: 28882 km

Engine Capacity: 1968 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 4 mm Rear Left Side: Goodyear 4 mm

Front Right Side: Goodyear 4 mm Rear Right Side: Goodyear 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,831.14	8,181.50	1,649.64	16.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,310.00	8,350.00	4,960.00	37.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,141.14	16,531.50	6,609.64	28.56
+ GST 7.00/7.00% (S\$)	1,619.88	1,157.21	462.67	28.56
Nett Amount (S\$)	24,761.02	17,688.71	7,072.31	28.56

INSPECTION

Date of Assignment: 05/05/2022

Date Inspected: 06/05/2022 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2022)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2168X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*WING DOOR WITH WINDOW OPE REAR BOOT LID (RH)	Dented	2,769.42 FS	*2,769.42 FS
2	1	*1K WINDOW ADHESIVE	Necessary	51.44 FS	*51.44 FS
3	1	*ALL PURPOSE CLEANER	Necessary	102.88 FS	*102.88 FS
4	1	*PRIMER	Necessary	30.27 FS	*30.27 FS
5	1	*ACTIVATOR	Necessary	26.27 FS	*26.27 FS
6	2	*APPLICATOR	Necessary	22.32 FS	*22.32 FS
7	2	*RIVETTED CAP NUT	Necessary	5.28 FS	*5.28 FS
8	1	*ALU -LAMIN INSULATION BOOT LID INSULATION	Necessary	43.65 FS	*43.65 FS
9	1	*WING DOOR WITH WINDOW OPE REAR BOOT LID (LH)	Dented	2,769.42 FS	*2,769.42 FS
10	1	*1K WINDOW ADHESIVE	Necessary	51.44 FS	*51.44 FS
11	1	*PRIMER	Necessary	30.27 FS	*30.27 FS
12	1	*ACTIVATOR	Necessary	26.27 FS	*26.27 FS
13	4	*RIVETTTED CAP NUT	Necessary	19.32 FS	*19.32 FS
14	1	*VW SIGN BLACK /BRIGHT CHRO	Necessary	100.86 FS	*100.86 FS
15	1	*INSCRIPTION CHROME NAME PLATE -CADDY	Necessary	71.57 FS	*71.57 FS
16	1	*DOOR SEAL BOOT LID SEAL (CTR)	Not Necessary	77.81 FS	*- FS
17	2	*FLUORESCENT STRIP BOOT LID REFLECTOR (STICKER)	Not Necessary	70.18 FS	*- FS
18	1	*HOOD LOCK WITH MICRO SWIT LHS BOOT LID LOCK (LOWER)	Not Necessary	99.02 FS	*- FS
19	1	*HOOD LATCH RHS BOOT LID LOCK (LOWER)	Not Necessary	96.89 FS	*- FS
20	2	*RIVETTED CAP NUT	Necessary	5.28 FS	*5.28 FS
21	1	*ALU-LAMIN INSULATION BOOT LID INSULATION	Necessary	43.65 FS	*43.65 FS
22	1	*COVER FOR BUMPER SATIN BI REAR BUMPER	Broken	791.24 FS	*791.24 FS
23	1	*CAP SATIN BLACK TOWING COVER	Cut	52.01 FS	*52.01 FS
24	1	*BUMPER REINFORCEMENT	Dented	650.26 FS	*650.26 FS
25	1	*GUIDE PIECE BUMPER SIDE BRACKET (LH)	Not Necessary	30.96 FS	*- FS
26	1	*GUIDE PIECE BUMPER SIDE BRACKET (SIDE)	Not Necessary	30.96 FS	*- FS
27	10	*GROMMET	Necessary	17.00 FS	*17.00 FS
28	10	*RIVET	Necessary	5.70 FS	*5.70 FS
29	1	*REFLECTOR RHS REFLECTOR	Broken	68.91 FS	*68.91 FS
30	1	*REAR APRON REAR END PANEL	Not Necessary	299.03 FS	*- FS
31	1	*ZINC SPRAY	Not Necessary	72.86 FS	*- FS
32	1	*2K-BODY ADHESIVE	Not Necessary	469.52 FS	*- FS
33	1	*SEALANT CAN BE SPRAYED	Not Necessary	66.78 FS	*- FS
34	1	*COVER FOR LOCK CARRIER TI END PANEL TRIM COVER	Not Necessary	174.76 FS	*- FS
35	4	*CAP TITANIUM BLACK	Not Necessary	12.16 FS	*- FS
36	4	*SPEED NUT	Not Necessary	10.56 FS	*- FS
37	1	*WHEELHOUSE PROTECTOR RHS REAR FENDER LINER	Not Necessary	138.15 FS	*- FS
38	1	*70KM/H STICKER	Necessary	12.00 FS	*12.00 FS
39	1	*REVERSE SENSOR	Broken	400.00 FS	*400.00 FS
40	1	*STICKER	Necessary	14.77 FS	*14.77 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 9,831.14 8,181.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	5,040.00	2,520.00
2	SPRAY PAINT	New	4,000.00	2,400.00
3	R&R LHS REAR BOOT LID GLASS	New	840.00	840.00
4	R&R RHS REAR BOOT LID GLASS	New	840.00	840.00
5	TRANSFER LHS BOOT LID MECHANISM	New	840.00	420.00
6	TRANSFER RHS BOOT LID MECHANISM	New	840.00	420.00
7	B&P CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
8	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
9	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (\$)			13,310.00	8,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >