



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2206303
INV Date 11/10/2022
Reference CC4/LPC22004153/Kpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 3118U
Insured Veh. GBB 7796G
Claim No. 22/22/22/VC05/025732
Policy No. Z22VC05010826
Accident Date 27/04/2022
Inspection Date 25/05/2022

| Description | Total |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC4/LPC22004153/Kpa3q2

Date: 11/10/2022

Code: LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|----------------------|-----------------------|------------|
| Insured Veh. | GBB 7796G | Veh. Inspected | GBF 3118U |
| Policy No. | Z22VC05010826 | Coverage (\$) | 0.00 |
| Claim No. | 22/22/22/VC05/025732 | Excess (\$) | 0.00 |
| Assign From | ENG HUEY NI | Assign Date | 04/05/2022 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|----------|
| Make & Model | MITSUBISHI CANTER | c.c | 2998 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | FEA01BA20259 | Colour | WHITE |
| Odometer | 242284 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | NIL |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|----------------|-------------|---------|
| R/H Front Tyre | 185/75 R15 | YOKOHAMA | 9 mm |
| L/H Front Tyre | 185/75 R15 | YOKOHAMA | 9 mm |
| R/H Rear Tyre | 185/75 R15 (D) | BRIDGESTONE | 7/7 mm |
| L/H Rear Tyre | 185/75 R15 (D) | BRIDGESTONE | 7/7 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 27/04/2022 | Inspection Date | 25/05/2022 |
| Survey held at | LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3118U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | TAILLAMP | CRACKED | 200.45 | 200.45 |
| 1 | TAILLAMP BRACKET | TO REPAIR SEE LABOUR | 76.45 | - |
| 1 | REAR NUMBER PLATE LAMP | SERVICEABLE | 107.97 | - |
| 1 | FRONT BUMPER | BENT | 795.48 | 795.48 |
| 2 | FRONT BUMPER BRACKET @\$169.30 | BENT | 338.60 | 338.60 |
| 2 | FRONT BUMPER SIDE RUBBER @\$321.60 | N/S DENTED | 643.20 | 321.60 |
| 1 | FRONT GRILLE | MTG CRACKED | 444.17 | 444.17 |
| 1 | FRONT PANEL | BENT | 1,030.65 | 1,030.65 |
| 1 | FUSO EMBLEM | NECESSARY | 154.98 | 154.98 |
| 1 | N/S HEADLAMP | MTG CRACKED | 501.40 | 501.40 |
| 1 | N/S FRONT SIGNAL LAMP | SERVICEABLE | 266.55 | - |
| 1 | HORN | SERVICEABLE | 123.70 | - |
| 1 | FRONT WINDSCREEN RUBBER | NOT NECESSARY | 356.54 | - |
| 1 | AIRCON BLOWER UNIT | HOUSING CRACKED | 2,584.78 | 2,584.78 |
| 1 | AIRCON SUCTION HOSE | SERVICEABLE | 365.60 | - |
| | LESS 20% DISCOUNT | | -1,598.10 | - |
| | LESS 25% DISCOUNT | | - | -1,593.03 |
| | | | 6,392.42 | 4,779.08 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | REAR NUMBER PLATE (SN) | SERVICEABLE | 40.00 | - |
| 2 | TAILGATE HOOK BRACKET @\$25.00 (SN) | TO REPAIR SEE LABOUR | 50.00 | - |
| 1 | 60KM/H STICKER (SN) | NOT NECESSARY | 15.00 | - |
| 1 | SET COMPANY LOGO STICKER (SN) | NOT NECESSARY | 600.00 | - |
| 1 | FRONT NUMBER PLATE (SN) | BENT | 40.00 | 20.00 |
| | | | 745.00 | 20.00 |
| <u>LABOUR</u> | | | | |
| | TO PUTTY AND SPRAY PAINT. | | 800.00 | 600.00 |
| | TO REMOVE & REFIX FRONT WINDSCREEN GLASS . | | 100.00 | 60.00 |

Report Ref No. CC4/LPC22004153/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|---|-----------|---------------------------|-------------------|
| | TO REMOVE & REFIX FRONT DASHBOARD ASSY . | | 340.00 | 250.00 |
| | TO REPLACE AIRCON COOLING COIL UNIT ,VACUUM AND REFILL GAS. | | 100.00 | 100.00 |
| | LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF TAILLAMP BRACKET AND TAILGATE HOOK BRACKET. | | 800.00 | 650.00 |
| | | | 2,140.00 | 1,660.00 |
| | GRAND TOTAL | | 9,277.42 | 6,459.08 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 5,150.00 |

Report Ref No. CC4/LPC22004153/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3118U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3118U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 3118U

RE-INSPECTION

