

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22004158/KVCM4**Date:** 12/09/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001778311

Claimant Vehicle No : SLF7058P**Insured Vehicle No :** S999T

Date of Loss: 28/04/2022

Nature of Claim: TP Claim No: 273609

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLF7058P**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P520375875

Reg. Date: 06/09/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0346707

Colour: Metallic Grey

Odometer: 371409 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: KPATOS 8 mm

Rear Left Side: Tourador 6 mm

Front Right Side: KPATOS 8 mm

Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 6,461.63 | 2,690.48 | 3,771.15 | 58.36 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,050.00 | 1,195.00 | 855.00 | 41.71 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,511.63 | 3,885.48 | 4,626.15 | 54.35 |
| Approved Total (Overridden) (S\$) | | 3,100.00 | | |
| Nett Amount (S\$) | 8,511.63 | 3,100.00 | 5,411.63 | 63.58 |

INSPECTION

Date of Assignment: 05/05/2022

Date Inspected: 18/05/2022

Inspected At:

Autoworx House - Sin Ming (HQ)

176 SIN MING DRIVE #02-01

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2022)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF7058P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-------------|-------------|--------------|
| 1 | 1 | | *REAR BOOT LID | Bent | 986.30 FL | *986.30 FL |
| 2 | 1 | | *REAR BOOT LOGO | Necessary | 82.60 FL | *66.40 FL |
| 3 | 1 | | *REAR BOOT EMBLEM MAZDA 3 | Necessary | 63.80 FL | *31.40 FL |
| 4 | 1 | | *REAR BOOT EMBLEM SKYACTIVE TECHNOLOGY | Necessary | 75.60 FL | *32.40 FL |
| 5 | 1 | | *REAR BOOT LOCK | Dented | 291.30 FL | *186.00 FL |
| 6 | 1 | | *REAR BOOT WEATHERSTRIP | Serviceable | 326.80 FL | *- FL |
| 7 | 2 | | *REAR BOOT LAMP | Serviceable | 993.60 FL | *- FL |
| 8 | 2 | | *REAR TAIL LAMP ASSY | Serviceable | 1,136.80 FL | *- FL |
| 9 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 583.20 FL | *583.20 FL |
| 10 | 1 | | *REAR BUMPER | Buckled | 1,178.50 FL | *1,047.30 FL |
| 11 | 1 | | *REAR BUMPER TOW COVER | Serviceable | 63.70 FL | *- FL |
| 12 | 2 | | *REAR BUMPER REFLECTOR | Serviceable | 427.80 FL | *- FL |
| 13 | 1 | | *END PANEL GARNISH | Cracked | 328.60 FL | *180.10 FL |
| 14 | 1 | | *END PANEL | Repair | 769.20 FL | *- FL |
| 15 | 1 | | *SET REVERSE SENSOR | Dented | 250.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (S\$) | 7,557.80 | 3,313.10 |
| - List Item Discount on L Items 15.00/20.00% (S\$) | 1,096.17 | 622.62 |
| Total Parts (S\$) | 6,461.63 | 2,690.48 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS | New | 850.00 | 500.00 |
| 2 | TO INSTALL REVERSE SENSOR | New | 100.00 | 50.00 |
| 3 | TO CHECK WIRING SYSTEM | New | 50.00 | 15.00 |
| 4 | TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS | New | 850.00 | 600.00 |
| 5 | TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS | New | 100.00 | 0.00 |
| 6 | TO APPLY RUST PROOFING ON AFFECTED AREAS | New | 100.00 | 30.00 |
| Gross Labour Cost (S\$) | | | 2,050.00 | 1,195.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >