

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCY 6968B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RH (BENT)	NOT CONSISTENT WITH THE IMPACT	1,597.40	-
1	REAR DOOR RUBBER (AT DOOR) RH	SERVICEABLE	217.30	-
1	REAR DOOR RUBBER (AT DOOR) BTM RH	SERVICEABLE	79.50	-
1	REAR DOOR RUBBER (AT BODY) RH	SERVICEABLE	310.60	-
1	REAR DOOR LOCK RH	TO REPAIR SEE LABOUR	595.70	-
1	SIDE SKIRT RH	SERVICEABLE	633.30	-
7	SIDE SKIRT CLIPS	NOT NECESSARY	80.50	-
1	REAR FENDER RH (BENT)	NOT CONSISTENT WITH THE IMPACT	1,137.00	-
1	REAR FENDER COWLING RH	SERVICEABLE	202.20	-
8	REAR FENDER COWLING CLIPS	NOT NECESSARY	36.00	-
1	REAR WINDSCREEN MLDG	NOT NECESSARY	967.20	-
1	REAR WINDSCREEN MLDG BTM - CHECK PRICE (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER	BUCKLED / MTG CRACKED	695.80	695.80
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	63.40	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	117.40	117.40
8	REAR BUMPER CLIPS	NECESSARY	38.40	38.40
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	423.90	-
1	REAR AIR VENT RH	SERVICEABLE	144.90	-
	LESS 25% DISCOUNT		-1,835.13	-212.90
			5,505.37	638.70
	SPECIAL NETT ITEMS			
1	INNER SEAL (SN)	NOT NECESSARY	20.00	-
	WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
1	SET PARKING SENSOR 4-IN-1 (SN)	SERVICEABLE	400.00	-
			460.00	-
	LABOUR			
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-

Report Ref No. CS/AIS22004160/Kvcm4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	NOT NECESSARY	60.00	-
	TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.		60.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR FENDER RH. TO KNOCK & REPAIR REAR WHEELHOUSE PANEL RH, REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF REAR DOOR LOCK RH AND REAR BUMPER REINFORCEMENT.		800.00	200.00
	TO SPRAY REAR DOOR RH, SIDE SKIRT RH, REAR FENDER RH, REAR BUMPER, REAR END PANEL.		1,000.00	200.00
			2,480.00	450.00
	GRAND TOTAL		8,445.37	1,088.70

RECOMMENDED COST OF REPAIRS			1,088.70
-----------------------------	--	--	----------

Report Ref No. CS/AIS22004160/Kvcm4

KONG SENG CHEONG

Licensed Appraiser