

ASS. REC. BY: Steve

CS/AIS 2200461/EQC

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. 2022 22004739SL  
 Sum Insured: \_\_\_\_\_ Excess: \$700/-  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SL2 746 C Yr Regn: 23/4/18  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai i30 c.c. 1353  
 Colour: Grey A/C: Insured / Std / Nil / NA  
 Sp. Reading: 67986 T/Radio: Insured / Std / Nil / NA  
 Eng/No: \_\_\_\_\_  
 C/No: TMAH 3513 VJJ 06 4981  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 225/40ZR18  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front R/Bal. 4 mm Rear R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 29/4/22 D.O.I. 6/5/22  
 Survey held at Komeco  
 Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 DAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 8 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MIV-73k</u>
<u>06/05/22@1.35pm</u>	<u>revert to AIS via Merimen.</u>
<u>06/05/22@5.38pm</u>	<u>Sharon informed C/A &amp; ex:\$700 by email.</u>
<u>06/05/22@5.46pm</u>	<u>Informed wksp C/A &amp; ex:\$700 by email.</u>
<u>25/05/22</u>	<u>Confirmed final fig \$13033.29, 8 days. (Red \$20989.70, 62%)</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 25/05 Typist  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: OD  
 Lump Sum / L.S.F. (\$ 13033.29)

Days Of Repair: 8  
 Resurvey No. of Trip: 1  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
S + RS: \$1	
Photos	
Others	
TOTAL	



**HYUNDAI**  
 MOTOR MOTORS PTE. LTD.  
 100, North Bridge Road, Singapore 079200  
 TEL: 65472 2288 FAX: 65471 1111  
 HONGKONG BRANCH

( GST REGISTRATION NO: MR-8500364-4 )

Date : 4/5/2022  
 11 MAR 2022

**ALLIANZ Insurance Singapore Pte Ltd**  
 Attn: Motor Claims Department

Vehicle number : **SLZ 746 C**  
 Make and model : **I30 1.4 GLS 5DR DCT TURBO**  
 Registration Date : **23/04/2018**  
 Chassis number : **TMAH3513VJJ064981**  
 Engine number : **G4LDHD120582**

Job No. :

Owner name : **Tan Jing Felix**

Date of Acc : **29/04/2022**

Policy number : **SP2001255858-01**

Claim Type : **OD-Excess TBC**

**Items :**

**Estimate**

Items	Part No.	Unit	Estimate
1 BUMPER CLIP X10 / <i>nec</i>	86595-2T500	\$	12.00
2 UPPER GRILLE CLIP X6 / <i>nec</i>	14206-08250B	\$	3.60
3 GRILLE-RADIATOR / <i>BR</i>	86351-G4010	\$	480.20
4 CR PIECE 1-RADIATOR GRILLE / <i>BR</i>	86355-G4100	\$	255.90
5 STRIP ASSY-FR BUMPER UPR / <i>CR4</i>	86357-G4000	\$	64.89
6 EMBLEM-SYMBOL MARK / <i>BR</i>	86300-G4100	\$	26.10
7 COVER-RADIATOR GRILLE,UPR / <i>CR4</i>	86362-G4000	\$	150.44
8 COVER-FR BUMPER / <i>BR</i>	86511-G4000	\$	836.64
9 GRILLE-FRONT BUMPER / <i>BR</i>	86561-G4000	\$	123.41
10 BRACKET-FR BUMPER SIDE,LH ?	86513-G4000	\$	74.93
11 BRACKET-FR BUMPER SIDE,RH ?	86514-G4000	\$	74.93
12 MOULDING-FRT BPR LICENSE PLATE / <i>BR</i>	86519-G4000	\$	41.83
13 ABSORBER-FRONT BUMPER ENERGY / <i>BR</i>	86520-G4050	\$	224.91
14 COVER-FR BUMPER FOG LAMP,LH ?	86563-G4040	\$	88.99
15 COVER-FR BUMPER FOG LAMP,RH X	86564-G4040	\$	88.99
16 BRACKET-FRT BUMPER MOUNTING,LH ?	86553-G4000	\$	44.75
17 BRACKET ASSY-FR BUMPER UPR SUP X2 / <i>BR</i>	86556-F2000	\$	16.80
18 BRACKET-FRT BUMPER MOUNTING,RH ?	86554-G4000	\$	44.75
19 PIECE-RADIATOR GRILLE NO.2 ?	86353-G4000	\$	158.30
20 PIECE-RADIATOR GRILLE NO.3 ?	86354-G4000	\$	112.86
21 GARNISH-RADIATOR GRILLE,UPR / <i>BR</i>	86356-G4000	\$	73.90
22 DUCT ASSY-AIR CURTAIN,LH ?	86567-G4030	\$	47.68
23 DUCT ASSY-AIR CURTAIN,RH X	86568-G4030	\$	47.68
24 STIFFNER-FR BPR LWR X	86571-G4000	\$	174.25
25 CAP ASSY-FR BPR X	86588-G4000	\$	24.84
26 LIP ASSY-FRONT BUMPER ?	86591-G4000	\$	161.80
27 LAMP ASSY-FRONT FOG,LH X	92201-G4000	\$	265.10
28 LAMP ASSY-FRONT FOG,RH X	92202-G4000	\$	265.10
29 LAMP ASSY-DAY RUNNING LIGHT,LH ?	92207-G4100	\$	642.50
30 LAMP ASSY-DAY RUNNING LIGHT,RH X	92208-G4100	\$	642.50

8-43

Vehicle number : **SLZ 746 C**  
 Make and model : **I30 1.4 GLS 5DR DCT TURBO**  
 Registration Date : **23/04/2018**  
 Chassis number : **TMAH3513VJJ064981**  
 Engine number : **G4LDHD120582**

Job No. :  
 Owner name : **Tan Jing Felix**  
 Date of Acc : **29/04/2022**  
 Policy number : **SP2001255858-01**  
 Claim Type : **OD-Excess TBC**

Items :	Estimate
31 LAMP ASSY-HEAD,LH <i>OR</i>	92101-G4030 \$ 1,686.80
32 LAMP ASSY-HEAD,RH <i>?</i>	92102-G4030 \$ 1,686.80
33 BEAM COMPLETE-FR BUMPER <i>M</i>	64900-G4000 \$ 636.40
34 CARRIER ASSY-FRONT END MODULE <i>OR</i>	64101-G4000 \$ 1,332.76
35 HORN ASSY-LOW PITCH <i>X</i>	96610-G3000 \$ 73.50
36 PANEL ASSY-HOOD <i>DD</i>	66400-G4000 \$ 1,502.54
37 HINGE ASSY-HOOD,LH <i>GT</i>	79110-G3000 \$ 49.50
38 HINGE ASSY-HOOD,RH <i>GT</i>	79120-G3000 \$ 49.50
39 PAD-HOOD INSULATING <i>CRU</i>	81125-G4000 \$ 419.30
40 LATCH ASSY-HOOD <i>?</i>	81130-G3900 \$ 114.80
41 CABLE ASSY-HOOD LATCH RELEASE <i>?</i>	81190-G3800 \$ 12.40
42 SIDE BUMPER-HOOD OVERSLAM X2 <i>X</i>	17372-09520B \$ 2.00
43 FRT BUMPER-HOOD OVERSLAM X2 <i>X</i>	17377-22036B \$ 7.60
44 COVER ASSY-COWL TOP SIDE,LH <i>CR4</i>	86152-G4000 \$ 73.04
45 COVER ASSY-COWL TOP SIDE,RH <i>CR4</i>	86153-G4000 \$ 136.55
46 COVER ASSY-COWL TOP <i>X</i>	86150-G4900 \$ 683.22
47 RETAINER-COWL TOP COVER MTG X4 <i>AEC</i>	86155-2H100 \$ 5.60
48 PANEL ASSY-FENDER,LH <i>DD</i>	66310-G3000 \$ 1,061.90
49 PANEL ASSY-FENDER,RH <i>X</i>	66320-G3000 \$ 1,061.90
50 FILLER NECK ASSY-RADIATOR <i>?</i>	25329-F3300 \$ 28.80
51 BLOWER ASSY <i>?</i>	25380-F3300 \$ 567.50
52 HOSE-RADIATOR INLET <i>?</i>	25411-F2250 \$ 48.10
53 HOSE ASSY-RADIATOR,UPR <i>?</i>	25414-F3300 \$ 42.40
54 HOSE ASSY-RADAATOR,LWR <i>?</i>	25415-F3300 \$ 59.10
55 GUARD-AIR,LH <i>CR1</i>	29136-G4200 \$ 73.04
56 GUARD-AIR,RH <i>CR1</i>	29134-G4200 \$ 73.04
57 CONDENSER ASSY-COOLER <i>DD</i>	97606-F2200 \$ 745.10
58 RADIATOR ASSY <i>?</i>	25310-G4300 \$ 1,009.69
59 ANTIFREEZER <i>?</i>	99H94-AQ710H \$ 95.60
60 AIR GUIDE-INTERCOOLER <i>?</i>	28272-2A690 \$ 31.00
61 COOLER ASSY-INTER <i>?</i>	28270-03110 \$ 915.40
62 DUCT ASSY-EXTENSION <i>?</i>	28220-G3000 \$ 143.20
63 DUCT-EXTENSION <i>?</i>	28212-G3000 \$ 3.50
64 SHIELD-AIR INTAKE <i>?</i>	28213-G3000 \$ 8.60
65 DUCT-AIR "B" <i>?</i>	28210-G3000 \$ 96.80
66 RETAINER-COWL TOP COVER MTG X2 <i>PR</i>	86155-2H100 \$ 2.80
67 WIRING ASSY-BATTERY <i>?</i>	91850-G4490 \$ 1,239.41
68 WIRING ASSY-FEM <i>?</i>	91870-G4060 \$ 236.16
69 WIRING ASSY-FRT <i>?</i>	91228-G4631 \$ 7,187.25
70 WIRING ASSY-CONTROL <i>?</i>	91420-G4010 \$ 3,738.61
	<b>\$ 32,211.78</b>
Less 20% Discount	<b>\$ 6,442.36</b>
Material total	<b>\$ 25,769.42</b>

Vehicle number : **SLZ 746 C**  
 Make and model : I30 1.4 GLS 5DR DCT TURBO  
 Registration Date : 23/04/2018  
 Chassis number : TMAH3513VJJ064981  
 Engine number : G4LDHD120582

Job No. :  
 Owner name : Tan Jing Felix  
 Date of Acc : 29/04/2022  
 Policy number : SP2001255858-01  
 Claim Type : **OD-Excess TBC**

**Body, Paint & Labour Items :**

	<i>Estimate</i>
1 To carry out accident body repair 380 x 4	\$ 3,040.00 1520
2 Complete putty and spray paint all affected areas 340 x 4	\$ 2,040.00 1360

**Labour Charges:**

	<i>Estimate</i>
3 TO REFOCUS BOTH FRT HEAD LAMP (S.NETT)	\$ 40.00 ✓
4 TO SUPPLY BONNET SEALANT (S.NETT)	\$ 100.00 ✓
5 TO VACUUM & TOP UP AIRCON GAS (S.NETT)	\$ 140.00 ✓
6 TO SUPPLY & INSTALL FRT NUMBER PLATE (S.NETT)	\$ 40.00 ✓ OR
7 TO REPAIR CHASSIS MEMBER (S.NETT)	\$ 320.00 ?
8 TO PUT ON CHASSIS BENCH ALIGNER	\$ 320.00 ?
9 TO R&I DASHBOARD ASSY TO FACILITATE REPAIR (S.NETT)	\$ 570.00 ?
10 TO RENEW FRT WIRING ASSY & REPROGRAM (S.NETT)	\$ 570.00 ?
11 TO RENEW CONTROL WIRING ASSY & REPROGRAM (S.NETT)	\$ 570.00 ?
12 TO RENEW BATTERY / FEM WIRING & REPROGRAM (S.NETT)	\$ 380.00 ?
<b>Total</b>	<b>\$ 33,840.62 33899.42</b>
Excess	
Add GST 7%	

**Grand Total**

\*\*\* Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out\*\*\*

Steve CLKK)  
 6/5/22, 10:00a

OD- M M  
 Excess-?  
 PIP

My RLH  
 8 Lys

LKK Auto Services to notify the Repairer of the following:

- To resurvey before repair
- To display damaged parts
- Parts prices are subject to final approval
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved

is subject to final approval from insurance company

Acknowledged by Repairer  
 Signature:  
 Date: