

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004165/GQCQ2**Date:** 12/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00011322100
<b>Claimant Vehicle No :</b>	GBD3186H	<b>Insured Vehicle No :</b>	SMQ9147H
Date of Loss:	07/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202390/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBD3186H</b>	Engine No:	1KD2421852
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35YX0K203291
Reg. Date:	29/08/2014 (Man. Year: 2014)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,196.00	620.00	576.00	48.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	725.00	525.00	200.00	27.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,921.00</b>	<b>1,145.00</b>	<b>776.00</b>	<b>40.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>900.00</b>		
<b>(S\$)</b>	1,921.00	900.00	1,021.00	53.15
<b>+ GST 7.00/7.00% (S\$)</b>	134.47	63.00	71.47	53.15
<b>Nett Amount (S\$)</b>	<b>2,055.47</b>	<b>963.00</b>	<b>1,092.47</b>	<b>53.15</b>

**INSPECTION**

Date of Assignment:	13/06/2022		
Date Inspected:	05/05/2022	Inspected At:	Ethoz Group (ethoz) 22 TAMPINES ST 92 Singapore 528876
Estimated Period of Repair:	2.0 days		

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Sep 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD3186H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	398.00 FL	*- FL
2	1		*STEP GARNISH LH	Not Necessary	335.00 FL	*- FL
3	1		*HEAD LAMP WIT SIGNAL LAMP LH	Cut	800.00 FL	*800.00 FL
4	1		*HEAD LAMP LOWER MOULDING LH	Not Necessary	35.00 FL	*- FL
5	1		*COMPANY DECAL STICKER	Necessary	20.00 FS	*20.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					1,588.00	820.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					392.00	200.00
Total Parts (\$\$)					1,196.00	620.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	300.00	200.00
2	PAINTING AFFECTED PORTIONS	New	400.00	300.00
3	CHECK AND RECONNECT NECESSARY WIRING	New	25.00	25.00
<b>Gross Labour Cost (S\$)</b>			<b>725.00</b>	<b>525.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >