

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22004166/UQCE2

Date: 19/05/2022

REFERENCE

Insured/Claimant: HO KUM CHUAN Policy No: D18MPC0002588
Date of Loss: 21/04/2022 Nature of Claim: OD Claim No: MPC2022D0002083

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR5067L**
Make & Model: HYUNDAI AD AVANTE, 1.6 GLS (A) Engine No: G4FC9U668791
Reg. Date: 26/06/2009 (Man. Year: 2009) Chassis No: KMHDU41BR9U782844
Colour: Grey Odometer: 281245 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$40,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,127.20	949.60	4,177.60	81.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,190.00	2,340.00	66.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,657.20	2,139.60	6,517.60	75.29
Approved Total (Overridden) (S\$)		1,700.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	8,057.20	1,100.00	6,957.20	86.35

INSPECTION

Date of Assignment: 05/05/2022

Date Inspected: 25/04/2022 Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2022)
Parts: 143	HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR5067L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	498.00 FL	*498.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*REAR BUMPER O/S SIDE RETAINER	Necessary	29.00 FL	*29.00 FL
4	3		*REAR BUMPER O/S INNER SHIELD CLIPS	Not Necessary	10.50 FL	*- FL
5	1		*REAR O/S FENDER	Repair	1,806.00 FL	*- FL
6	6		*REAR O/S FENDER INNER SHIELD CLIPS	Not Necessary	21.00 FL	*- FL
7	1		*REAR O/S DOOR	Repair	1,743.00 FL	*- FL
8	16		*REAR O/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	88.00 FL	*- FL
9	1		*REAR O/S LOWER ARM	Not Necessary	239.00 FL	*- FL
10	1		*REAR O/S SHOCK ABSORBER SHAFT	Not Necessary	232.00 FL	*- FL
11	1		*SET REAR O/S WHEEL BEARING & HUB	Not Necessary	395.00 FL	*- FL
12	1		*REAR O/S SPORT RIM	Warped	650.00 FS	*500.00 FS
13	1		*REAR O/S WHEEL TYRE (195X65XR15)	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,146.50	1,062.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,019.30	112.40
Total Parts (\$\$)	5,127.20	949.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO CHECK & ADJUST WHEEL BALANCING & WHEEL ALIGNMENT	New	150.00	60.00
3	TO REMOVE & REFIX REAR O/S SHOCK ABSORBER SHAFT, LOWER ARM, WHEEL BEARING & NECESSARY PARTS	New	220.00	0.00
4	TO REMOVE & REFIX CARPET, FLOOR MAT, REAR O/S FENDER INNER GARNISH, REAR O/S DOOR INNER TRIM BOARD COVER FOR REPAIR	New	180.00	60.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR O/S DOOR & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,350.00	450.00
6	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,500.00	600.00
7	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	80.00	0.00
			Gross Labour Cost (S\$)	3,530.00
				1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >