9/20/22, 4:20 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG22004170/RPA3Q2

**Date:** 20/09/2022

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472519

Claimant Vehicle CNAFORM

No: SNA5904M Insured Vehicle No: SJX5620H

Date of Loss: 01/05/2022 Nature of Claim: TP Claim No: 4543910613SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SNA5904M

Make & Model: AUDI Q8, 3.0 TFSI QU TIP (A) Engine No: DCB051886

Reg. Date: 28/01/2019 (Man. Year: 2018) Chassis No: WAUZZZF13KD011200

Colour: Black Odometer: 31430 km

Engine Capacity: 2995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/50 R20 Rear Tyre Size: 275/50 R20
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		9,731.00	5,322.40	4,408.60	45.30
Miscellaneous Items		0.00	0.00	0.00	
Labour		6,352.00	2,852.00	3,500.00	55.10
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	16,083.00	8,174.40	7,908.60	49.17
	+ GST 7.00/7.00% (S\$)	1,125.81	572.21	553.60	49.17
	Nett Amount (S\$)	17,208.81	8,746.61	8,462.20	49.17
	+ Loss of Use (4.0 x S	\$100.00/day) (S\$)	400.00		
	+ Do	c/Search Fee (S\$)	2.00		
		Nett Liability (S\$)	9,148.61		

**INSPECTION** 

Date of Assignment: 11/05/2022

Date Inspected: Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

11/05/2022 Inspected At: 55 UBI ROAD 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER -UPPER	Deformed	1,451.00 FS	*1,160.80 FS
2	1		*REAR BUMPER -LOWER	Deformed	2,201.00 FS	*1,760.80 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	177.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Scratched	1,407.00 FS	*1,125.60 FS
5	1		*REAR BUMPER CLOSING ELEMENT -RH	Not Necessary	108.00 FS	*-FS
6	1		*REAR BUMPER TRIM -RH	Scratched	273.00 FS	*218.00 FS
7	1		*REAR BUMPER TRIM -CENTER	Scratched	271.00 FS	*216.40 FS
8	1		*BOOT LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
9	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,506.00 FS	*- FS
10	2		*REAR BUMPER SEAL -LH/RH	Not Necessary	32.00 FS	*- FS
11	1		*REAR BUMPER HOLDING STRAP	Not Necessary	206.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION -CENTER	Not Necessary	159.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION -RH	Not Necessary	75.00 FS	*- FS
14	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
15	2		*REAR WHEEL ARCH COVER -LH/RH	Necessary	794.00 FS	*635.20 FS
16	1		*REAR FOG LIGHT -RH	Cracked	257.00 FS	*205.60 FS
17	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
18	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	ett.	_		
				Total Parts (S\$)	9,731.00	5,322.40
			Report was unsubmitted during	this print-out		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER TO REPAIR REAR END PANELLING ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,800.00	600.00
3	TO RESPRAY REAR UPPER BUMPER ,REAR LOWER BUMPER BOT HREAR WHEEL ARCH TRIMS AND REAR END PANELLING	New	4,000.00	1,700.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		6,352.00	2,852.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >