

SJC 3759R.

Toyota Vios. 1497cc.

TP Lon Pec

Xiao Tony

MR0531449305041872

Rees	Number Plate.	Defend	30(SN) ✓
Rees	Number Plate Holder.	Defend	30(SN) ✓
Rees	Bumper	Distorted	495.40 ✓
Rees	Bumper Clips.	new	30(SN) ✓
Rees	Bumper Side Holder x 02	new	55.1 x 2 = 110.20 ✓
Rees	Bumper Reflector x 02	Cracked	105.2 x 2 = 210.40 ✓
Reverse Sensor	Damaged		280(SN) 200(SN)
Rees	End Panel.	Dented	439.70 ✓
Rees	End Panel Top Garnish.	Cracked	230.60 ✓
Rees	End Panel Top Garnish Clips.	new	20(SN) ✓
Rees	End Panel Sealant.	new	60(SN) ✓
Rees	End Panel Bracket x 02		85.3 x 2 = 170.60
	ATP new		X

SJC3759R.

310.10.

Taillap x 02 ^{LH} cracked, ^{RH} ~~not~~ _{new}

$310.1 \times 2 = 620.20$

Taillap Panel x 02 Repair

$190.5 \times 2 = 381$ X

Bootlid Dented

595.90. ✓

Bootlid Lock Damaged

155.90. ✓

Bootlid Weatherstripe Lit

205.40. ✓

Bootlid Hinge x 02 ^{LH} ~~new~~

$70.5 \times 2 = 141$ X

Bootlid Outer Moulding Deformed

192.90. ✓

Toyota Logo

70.40. ✓

Vios Emblem.

72.50. ✓

E Emblem.

50.40. ✓

Spare Tyre Panel Top Board torn

175.60. ✓

Spare Tyre Panel Side Sponge x 02 ^{not} ~~new~~

$225.1 \times 2 = 450.20$

X

SJC 3759 R.

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor

To remove upholstery.

To spray tuff coat

To transfer bootlid fittings.

hist: 3315.10

less 25%: 2486.32

Special Net: 370

~~1200~~ 900

~~1100~~ 1000

~~50~~ 30

~~100~~ 50

~~150~~ 60

~~150~~ 60

~~150~~ 60.

Labour: 2160

total: ~~50~~ 16.32

h/s: 4K

06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4K