

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22004177/KQY3E2**Date:** 15/12/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00136112101

**Claimant Vehicle  
No :** SLQ7651T**Insured Vehicle  
No :** GBD5349S

Date of Loss: 03/05/2022

Nature of Claim: TP

Claim  
No: SNM22D202959/C02/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLQ7651T**Make & Model: NISSAN X-TRAIL, 2.0 CVT ABS 4WD S/R 7-STR  
(A)

Engine No: MR20002396C

Reg. Date: 21/07/2017 (Man. Year: 2017)

Chassis No: JN1JANT32Z0003308

Colour: Metallic Grey

Odometer: 79040 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18

Rear Tyre Size: 225/60 R18

Front Left Side: Falken 8 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Falken 8 mm

Rear Right Side: Yokohama 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,729.00	8,784.00	945.00	9.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	3,030.00	780.00	20.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,539.00</b>	<b>11,814.00</b>	<b>1,725.00</b>	<b>12.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,450.00</b>		
<b>(S\$)</b>	13,539.00	9,450.00	4,089.00	30.20
<b>+ GST 7.00/7.00% (S\$)</b>	947.73	661.50	286.23	30.20
<b>Nett Amount (S\$)</b>	<b>14,486.73</b>	<b>10,111.50</b>	<b>4,375.23</b>	<b>30.20</b>

INSPECTION

Date of Assignment: 06/05/2022

Date Inspected: 09/05/2022 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2022)
<b>Parts:</b>	M1-SUV	NISSAN X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ7651T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	360.00 F	*360.00 F
2	1		*REAR BUMPER REINFORCEMENT	Bent	320.00 F	*320.00 F
3	6		*REAR BUMPER CLIP	Necessary	12.00 F	*12.00 F
4	1		*REAR TAILGATE	Cracked	2,400.00 F	*2,400.00 F
5	1		*TAILGATE EMBLEM X-TRAIL	Necessary	75.00 F	*75.00 F
6	1		*TAILGATE LOGO	Necessary	50.00 F	*50.00 F
7	1		*TAILGATE REFLECTOR	N/S Cracked / O/S Serviceable	170.00 F	*85.00 F
8	1		*REAR WINDSCREEN GLASS	Shattered	1,000.00 F	*1,000.00 F
9	1		*TAILGATE INNER TRIM BOARD	Serviceable	210.00 F	*- F
10	1		*REAR END PANEL OUTER	Bent	280.00 F	*280.00 F
11	1		*REAR LH FENDER	Buckled	980.00 F	*980.00 F
12	1		*REAR LH FENDER TRIANGLE GLASS	Necessary	150.00 F	*150.00 F
13	1		*REAR LH FENDER WHEEL ARP GARNISH	Distorted	180.00 F	*180.00 F
14	1		*REAR LH FENDER LH INNER GARNISH	Deformed	350.00 F	*350.00 F
15	2		*TAILLAMP	Cracked	420.00 F	*420.00 F
16	1		*FRONT BUMPER	Buckled	380.00 F	*380.00 F
17	1		*FRONT BUMPER REINFORCEMENT	Repair	300.00 F	*- F
18	6		*FRONT BUMPER CLIP	Necessary	12.00 F	*12.00 F
19	1		*REAR PANEL INNER TOP GARNISH	Dented	70.00 F	*70.00 F
20	1		*REAR WIPER MOTOR	Jammed	405.00 F	*405.00 F
21	1		*TAILGATE OUTER CHROME MOULDING	Dented	90.00 F	*90.00 F
22	1		*TAILGATE INNER LOCK	Dented	370.00 F	*370.00 F
23	1		*REAR BUMPER REINFORCEMENT BRACKET LH	Bent	95.00 F	*95.00 F
24	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
25	1		*REAR LH FENDER GLASS GUM	Necessary	30.00 FS	*30.00 FS
26	1		*REVERSE CAMERA	Serviceable	350.00 FS	*- FS
27	1		*REVERSE SENSOR	Dented	250.00 FS	*250.00 FS
28	1		*REAR CAMERA	Missing	380.00 FS	*380.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **9,729.00**    **8,784.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	100.00	100.00
2	TO REMOVE AND REFIX REAR SEAT, CARPAT, TOP ROOF LINING, VACUUM AND WASH CUSHION	New	120.00	100.00
3	TO PUTTY AND RESPRAY ON RR BUMPER, RR PANEL, RR BOTH FENDERS, TAILGATE, AND REAR COMPARTMENT	New	1,200.00	1,000.00
4	TO REMOVE AND REFIX FRT BUMPER, GRILLE, HEADLAMP, KNOCK AND REPAIR FRT LH FENDER AND RE-ALIGN TO	New	400.00	250.00
5	TO PUTTY AND RESPRAY ON FRT LH FENDER, FRT BUMPER AND REINFORCEMENT	New	500.00	220.00
6	RUSTPROOFING	New	90.00	60.00
7	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
8	TO REMOVE & REFIX R BUMPER ASSY, TAILLAMPS, TAILGATE, TOP SPOILDER, RR WIPER ASSY, RR LOCK ASSY; CUT, WELD & RENEW RR END PANEL, RR LH FENDER; KNOCK & REPAIR RR COMPARTMENT, STRAIGHTEN RR RH CHASSIS, KNOCK AND REPAIR RR RH FENDER AND RE-ALIGN TO SAME	New	1,300.00	1,200.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,810.00</b>	<b>3,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >