9/13/22, 2:39 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22004179/EQY3Q2

13/09/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00115192101

**Claimant Vehicle** No:

SKX8256U

Insured Vehicle YQ2522L

No:

Date of Loss: 25/04/2022 Nature of Claim: TP

Claim No:

Engine No:

Chassis No:

Odometer:

SNM22D202880/C02/IRENE

MNTBBAB17Z0025454

Yes

HR16977685B

90557 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SKX8256U Reg No:

Make & Model: NISSAN SYLPHY, 1.6 (A)

Reg. Date: 29/12/2015 (Man. Year: 2015)

Colour: Silver

**Engine Capacity:** 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Pre-accident Condition: Handbrake (Serviceable): Engine Modification: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16 Front Left Side: Rear Left Side: Dunlop 4 mm Dunlop 4 mm Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,240.67	2,885.55	1,355.12	31.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,840.00	780.00	29.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	\$) 6,860.67	4,725.55	2,135.12	31.12
Approved Total (Overridden) (S	\$)	3,800.00		
(S	\$) 6,860.67	3,800.00	3,060.67	44.61
+ GST 7.00/7.00% (S	<b>\$)</b> 480.25	266.00	214.25	44.61
Nett Amount (S	\$) 7,340.92	4,066.00	3,274.92	44.61

**INSPECTION** 

Date of Assignment: 04/08/2022

Ethoz Group Ltd (HQ) 06/05/2022 Inspected At: 30 Bukit Batok Crescent Date Inspected:

Singapore 658075

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Sep 2022)

Parts: 143 NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX8256U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty Part No	. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Broken	701.80 FN	*653.00 FN
2	1	*REAR BUMPER RETAINER	Broken	97.00 FN	*48.50 FN
3	10	*REAR BUMPER CLIPS	Necessary	50.00 FN	*30.00 FN
4	1	*REAR BUMPER SIDE DUST COVER LH	Broken	40.00 FN	*40.00 FN
5	1	*TAILLAMP LH	Broken	434.50 FN	*434.50 FN
6	1	*REAR FENDER LH	Dented	1,583.50 FN	*1,583.50 FN
7	1	*REAR QUARTER GLASS LH	Not Necessary	569.50 FN	*- FN
8	1	*REAR SPORTS RIM LH	Cut	880.00 FN	*350.00 FN
9	1	*REAR DOOR LH (NPA)	Repair	0.00 FN	*- FN
10	1	*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
11	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
12	1	*REAR QUARTER GLASS SEALANT	Necessary	50.00 FS	*20.00 FS
F=Fra	anchise part. S=Sp	cNett. N=NettItemDisc.			
			Sub Total (S\$)	4,676.30	3,199.50
	- Nett Item Discount on N Items 10.00/10.00% (S\$)			435.63	313.95
			Total Parts (S\$)	4,240.67	2,885.55
			_		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR TO FACILITATE REPAIR	New	1,200.00	900.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	600.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
4	TO REMOVE AND REFIT REAR QUARTER GLASS LH	New	120.00	80.00
5	TO REPLACE AND BALANCER REAR RIM	New	80.00	80.00
6	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	S New	50.00	30.00
7	RUST PROOFING	New	50.00	30.00
	G	ross Labour Cost (S\$)	2,620.00	1,840.00
	Report was unsubmitted	d during this print-out.		

< END OF ESTIMATES >