



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EU 6336Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,078.00	-
1	REAR FENDER INNER SHIELD N/S	SERVICEABLE	228.00	-
1	REAR ROLL OVER STRUT N/S	SERVICEABLE	475.00	-
1	REAR SHOCK ABSORBER N/S	SERVICEABLE	589.00	-
1	REAR SHOCK ABSORBER MOUNTING N/S	SERVICEABLE	167.00	-
1	REAR LOWER ARM N/S	SERVICEABLE	487.00	-
1	REAR WHEEL KNUCKLE N/S	SERVICEABLE	594.00	-
1	REAR WHEEL KNUCKLE BEARING N/S	NOT NECESSARY	396.00	-
1	REAR WHEEL HUB N/S	SERVICEABLE	445.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	319.00	-
	LESS 5% DISCOUNT		-238.90	-
			4,539.10	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR ALLOY WHEEL "BBS" N/S (SN)	DENTED	950.00	800.00
1	REAR TYRE N/S (SN)	SERVICEABLE	280.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR FENDER SEALANT N/S (SN)	NOT NECESSARY	80.00	-
10	REAR FENDER INNER SHIELD CLIPS N/S @ \$5.50 (SN)	NOT NECESSARY	55.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			1,515.00	800.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTION. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S.		1,000.00	300.00
	SUPPLY SPRAY PAINT MATERIALS AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL.		800.00	250.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	NOT NECESSARY	100.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISCONNECT WIRE HARNESSSES OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY, INNER TRIM, INNER GARNISH, MOULDINGS TO FACILITATE REPAIR.		100.00	60.00
	TO REMOVE AND REFIT N/S REAR UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	NOT NECESSARY	100.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		100.00	60.00
	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK.	NOT NECESSARY	150.00	-
			2,400.00	670.00
<b>GRAND TOTAL</b>			<b>8,454.10</b>	<b>1,470.00</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,150.00</b>
---	--	--	--	-----------------

Report Ref No. CS/AGI22004181/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.