

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004182/AGA3Q2**Date:** 20/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900252171
Claimant Vehicle No :	SKU4054C	Insured Vehicle No :	SMQ8202M
Date of Loss:	29/04/2022	Nature of Claim:	TP
		Claim No:	6876223114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU4054C	Engine No:	PE10235105
Make & Model:	MAZDA 5, 2.0 5 DR WAGON (A)	Chassis No:	JM6CW1071F0121924
Reg. Date:	24/07/2015 (Man. Year: 2015)	Odometer:	90291 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,393.30	3,619.36	5,773.94	61.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,870.00	1,150.00	38.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,413.30	5,489.36	6,923.94	55.78
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	12,413.30	4,300.00	8,113.30	65.36
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	18/05/2022	Leang Automotive (Kaki Bukit)
Date Inspected:	18/05/2022 Inspected At:	AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6
		#01-68
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH FENDER	Dented	430.90 F	*430.90 FL
2	1		*FRONT LH FENDER INNER SHIELD	Deformed	142.90 F	*142.90 FL
3	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
4	1		*FRONT LH WHEEL RIM	Cut	800.00 FS	*500.00 FS
5	1		*FRONT LH TYRE	Not Necessary	250.00 FS	*- FS
6	1		*FRONT LH LOWER ARM	Not Necessary	391.30 F	*- FL
7	1		*FRONT LH KNUCKLE ARM	Not Necessary	408.00 F	*- FL
8	1		*FRONT LH WHEEL HUB C/W BEARING	Not Necessary	159.90 F	*- FL
9	1		*FRONT LH SHOCK ABSORBER	Not Necessary	275.00 F	*- FL
10	1		*FRONT LH DOOR	Dented	1,205.40 F	*1,205.40 FL
11	1		*FRONT LH DOOR LOCK	Not Necessary	468.00 F	*- FL
12	1		*FRONT LH DOOR WEATHERSTRIPE	Not Necessary	198.20 F	*- FL
13	1		*REAR LH DOOR	Dented	1,364.50 F	*1,364.50 FL
14	1		*REAR LH DOOR LOCK	Not Necessary	532.40 F	*- FL
15	1		*REAR LH DOOR WEATHERSTRIPE	Not Necessary	185.90 F	*- FL
16	1		*ROCKER PANEL OUTER SKIRTING	Deformed	680.50 F	*680.50 FL
17	1		*ROCKER PANEL OUTER SKIRTING CLIPS	Necessary	30.00 FS	*30.00 FS
18	1		*REAR LH WHEEL RIM	Not Necessary	800.00 FS	*- FS
19	1		*REAR BUMPER	Repair	962.40 F	*- FL
20	1		*REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
21	1		*REAR BUMPER SIDE HOLDER LH	Not Necessary	48.00 F	*- FL
					Sub Total (\$\$)	9,393.30 4,384.20
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 764.84
					Total Parts (\$\$)	9,393.30 3,619.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,200.00	1,000.00
3	WIRING	New	50.00	30.00
4	TO TRANSFER FRONT DOOR FITTINGS	New	150.00	80.00
5	TO TRANSFER REAR DOOR FITTINGS	New	150.00	80.00
6	TO DISMANTLE FRONT UNDERCARRIAGE	New	320.00	0.00
7	TO PERFORM WHEEL ALIGNMENT TEST	New	150.00	80.00
Gross Labour Cost (\$\$)			3,020.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >