

SK44054C. 2015 July.
Mazda 5 1998cc
JM6CW1071F0121924.

TP A16.
Cedica.

Front LH Fender	Dented	430.80 ✓
Front LH Fender Inner Shield	Dented	142.80 ✓
Front LH Fender Inner Shield Clips	per	30(SN) ✓
Front LH Wheel Rim.	cut	800(SN) 500(SN)
Front LH Tyre.	new	250(SN) +
Front LH lower Arm.	} XBP Nec	381.30 +
Front LH Knuckle Arm.		408. +
Front LH Wheel Hub c/w Bearing		158.80 +
Front LH Shock Absorber.		275 +
Front LH Door	Dented	1205.40. ✓
Front LH Door Lock	} XBP Nec	468 +
Front LH Door Weatherstripe		198.20 +
Rear LH Door	Dented	1364.50 ✓

SKU4054e

Reer LH Door Lock	} LH	532.40. X
Reer LH Door Weatherstripe		over 185.90 X
Rocker Panel Outer Skirting. Del		680.50 /
Rocker Panel Outer Skirting Clips.		30(SN) /
Reer LH Wheel Rim.	74E	800(SN) X
Reer Bumper	Regr	962.40. X
Reer Bumper Clips.	} LH	30(SN). X
Reer Bumper Side Holder LH.		48. X

3824.20

3058.36

S.N: 560

SKU 4054C.

Panel Beating.

Spray Painting.

Wiring.

To transfer front door fittings.

To transfer rear door fittings.

To dismantle front undercarriage

To perform wheel alignment test.

1870

~~1000~~ 600.

~~1200~~ 1000

~~50~~ 30

~~150~~ 80

~~150~~ 80

320 X

~~150~~ 80.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5489.36.

h/s: 4.3K. ✓

05 Days.