

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI22004188/Rtce2
	36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		I	Date:	26/05/2022
				Code:	FCI2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	XE 1537B	Veh. Inspected		WD 793B
	Policy No.		Coverage (\$)		0.00
	Claim No.	D22001288MFVS	Excess (\$)		0.00
	Assign From	JOANNE TAN JO ANN	Assign Date		05/05/2022
2.	Vehicle Particulars & Condition				
	Make & Model	VOLVO FMX370 84R	c.c		10837
	Engine No.	HIDDEN	Year of Reg.		2016
	Chassis No.	YV2X1E1G1GB755893	Colour		WHITE
	Odometer	171050 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	295/80 R22.5	FIREMAX		8 mm
	L/H Front Tyre	295/80 R22.5	FIREMAX		8 mm
	R/H Rear Tyre	295/80 R22.5 (D)	FIREMAX		8/8 mm
	L/H Rear Tyre	295/80 R22.5 (D)	FIREMAX		8/8 mm
4.	Description of Damages				
	THE VEHICLE SUS	JSTAINED DAMAGES AT THE FRONT PORTION.			
5.	General Information				
	Accident Date	16/04/2022	Inspect Date / T	ime	06/05/2022 ( 02:33 PM )
	Survey held at	51 KRANJI CRESCENT SINGAPORE 728661			
	Repairer	MEGASTONE HOLDINGS PTE LTD.			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$90,000.00				

Report Ref No. CS3/FCI22004188/Rtce2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser