

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004191/EVCE2

Date: 30/06/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00011492200

**Claimant Vehicle
No :** SBV68R

**Insured Vehicle
No :** SFP357R

Date of Loss: 04/05/2022

Nature of Claim: TP

Claim
No: SNM22D203024/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBV68R**

Make & Model: JAGUAR E-PACE, 2.0 S (A)

Engine No: 190508Y0195PT204

Reg. Date: 30/10/2020 (Man. Year: 2019)

Chassis No: SADCA2AXXKA616467

Colour: Red

Odometer: 25382 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/55 R19

Rear Tyre Size: 255/55 R19

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,491.40	2,435.94	3,055.46	55.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,921.00	2,921.00	1,000.00	25.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,412.40	5,356.94	4,055.46	43.09
+ GST 7.00/7.00% (S\$)	658.87	374.99	283.88	43.09
Nett Amount (S\$)	10,071.27	5,731.93	4,339.34	43.09

INSPECTION

Date of Assignment: 05/05/2022

Date Inspected: 11/05/2022

Estimated Period of Repair: 3.0 days

Inspected At: Wearnes automotive Pte Ltd (HQ)
45 LENG KEE ROAD
Singapore 159103

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jun 2022)

Parts: M1-SUV JAGUAR E-PACE 2.0 S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SBV68R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-BUMPER REAR	Dented	1,957.80 FS	*1,762.02 FS
2	1		*MOUNTING-BRACKET CTR	Cut	234.30 FS	*210.87 FS
3	10		*BUMPER NUT XF	Necessary	53.00 FS	*47.70 FS
4	1		*COVER-TWNG HK OPNNG	Crushed	33.40 FS	*30.06 FS
5	1		*PANEL VALANCE	Not Necessary	257.30 FS	*- FS
6	1		*BUMPER BEAM REAR XE	Not Necessary	714.30 FS	*- FS
7	1		*SENSOR (4PCS)	Cut (1Pc Only)	1,712.40 FS	*385.29 FS
8	1		*LAMP-FOG LH	Not Necessary	340.80 FS	*- FS
9	1		*ANTENNA	Not Necessary	43.80 FS	*- FS
10	1		*HEATSHIELD LH	Not Necessary	81.50 FS	*- FS
11	1		*HEATSHIELD LH	Not Necessary	62.80 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)

5,491.40

2,435.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, REAR TOW HOOK COVER, REINFORCEMENT, ETC	New	1,500.00	1,300.00
2	TO SPRAY REAR BUMPER, REINFORC ETC	New	1,800.00	1,000.00
3	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
			Gross Labour Cost (\$\$)	3,921.00
				2,921.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >