

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / (P) / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SBV 68R Yr Regn: 30/10/20  
 Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Jaguar F-Pace c.c. 1997  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 25387 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: SADCA9XXKA616A67  
 Gen. Cond: (Good) / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 255/55R19  
 R: 11

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<u>XX</u>	

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

(BS) / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front Rear  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 4/5/22 D.O.I. 11/5/22  
 Survey held at Wearnes  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MV-952K</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to?  
 1) \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Lump Sum / I.B.H. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_ \$ + RS. SI  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

**SERVICE ESTIMATE**

##### - C00001 SL: SERVICE SALES - PC  
 Ms Alexia Ho Wen Tsi  
 522 East Coast Road #17-01

Singapore 458966

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Ms Alexia Ho Wen Tsi

GST Reg.No:M28920628X  
 0 Page 1  
 Inv.No. . . : B&P  
 Inv.date. : 05/05/2022  
 WIP No. . . : 23674  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98164184  
 Reg.No. . . : SBV68R  
 Reg.date . . : 30/10/2020  
 Mileage ... : 0  
 Chassis No: SADCA2AXXKA616467

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR TOW HOOK COVER, REINFORCEMENT, ETC		0	1500.00	0/300		1,500.00	S
800	TO SPRAY REAR BUMPER, REINFORC ETC		0	1800.00	0/999		1,800.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		0	621.00	0 /		621.00	S
	COVER-BUMPER REAR / <i>DD</i>		1.0	EA	1957.80		1,957.80	S
	MOUNTING-BRACKET CTR / <i>CVT</i>		1.0	EA	234.30		234.30	S
	BUMPER NUT XF / <i>APC</i>		10.0	EA	5.30		53.00	S
	COVER-TWNG HK OPNNG / <i>CR4</i>		1.0	EA	33.40		33.40	S
	PANEL VALANCE X		1.0	EA	257.30		257.30	S
	BUMPER BEAM REAR XE ?		1.0	EA	714.30		714.30	S
	SENSOR / <i>CVT</i>		1.0	EA	428.10		1,712.40	S
	LAMP-FOG LH X		1.0	EA	340.80		340.80	S
	ANTENNA ?		1.0	EA	43.80		43.80	S

**SERVICE ESTIMATE**

#### - C00001 SL: SERVICE SALES - PC  
 Ms Alexia Ho Wen Tsi  
 522 East Coast Road #17-01

Singapore 458966

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Ms Alexia Ho Wen Tsi

GST Reg.No:M28920628X  
 Inv.No. . . : B&P 0 Page 2  
 Inv.date. . : 05/05/2022  
 WIP No. . . : 23674  
 Veh.In/Out:  
 \*Tel.No. . . : Mobile: 98164184  
 Reg.No. . . : SBV68R  
 Reg.date . . : 30/10/2020  
 Mileage . . : 0  
 Chassis No: SADCA2AXXKA616467

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEATSHIELD LH X	1.0 EA	81.50			81.50	S
	HEATSHIELD LH X	1.0 EA	62.80			62.80	S

*Steve (LKK)  
 11/5/22, 11-9am  
 Over R  
 P/P  
 3 4s*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**Labour Total** 3,921.00  
**Parts Total** 5,491.40  
**Package Total** 0.00

**Gross Total.** 9,412.40  
**Net.....** 9,412.40  
**GST @ 7.0%** 658.87  
**Total.....** 10,071.25  
**Paid.....** 0.00  
**Please Pay..** 10,071.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated