

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22004194/ETCN2**Date:** 02/06/2022**REFERENCE**

Insured/Claimant: LEO CHIN YU ZE (CHEN YUZE) Policy No: DMPCSNW00210832100

Date of Loss: 07/03/2022

Nature of Claim: OD

Claim No: SNM22D201661/C01/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMZ8244U</b>	Engine No:	30365775B38A15A
Make & Model:	BMW 216I, 1.5 D GT LED (A)	Chassis No:	WBA6V120505P14415
Reg. Date:	29/11/2019 (Man. Year: 2019)	Odometer:	27677 km
Colour:	Brown		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55R17	Rear Tyre Size:	205/55R17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	495.35	40.00	455.35	91.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,004.00	2,646.00	56.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>5,145.35</b>	<b>2,044.00</b>	<b>3,101.35</b>	<b>60.27</b>
<b>- Excess (\$\$)</b>	700.00	700.00	0.00	0.00
<b>(\$\$)</b>	4,445.35	1,344.00	3,101.35	69.77
<b>+ GST 7.00/7.00% (\$\$)</b>	311.17	94.08	217.09	69.77
<b>Nett Amount (\$\$)</b>	<b>4,756.52</b>	<b>1,438.08</b>	<b>3,318.44</b>	<b>69.77</b>

**INSPECTION**

Date of Assignment: 06/05/2022

Date Inspected: 09/05/2022 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance  
Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jun 2022)
Parts:	M1-MPV	BMW 216I 1.5 D GT LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMZ8244U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH REFLECTOR	Not Necessary	39.05 FS	*- FS
2	1		*REAR RH LIGHT IN THE SIDE PANEL	Not Necessary	376.30 FS	*- FS
3	1		*SUNDRIES	Necessary	80.00 FS	*40.00 FS
Total Parts (S\$)						495.35 40.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO MAKE GOOD REAR BUMPER AND RIGHT REAR FENDER	New	2,550.00	850.00
2	TO RESPRAY REAR BUMPER AND RIGHT REAR FENDER	New	1,923.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
<b>Gross Labour Cost (\$)</b>			<b>4,650.00</b>	<b>2,004.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >