



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 8804D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	EXT VIEW MIRROR LH (SN)	SCRATCHED	517.50	517.50
1	RR VIEW MIRROR LH (SN)	NOT NECESSARY	67.50	-
1	MIRROR CAPPING LH (SN)	NOT NECESSARY	58.50	-
1	SIDE FLASH-UNIT LH (SN)	SCRATCHED	139.50	139.50
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
			883.00	657.00
LABOUR				
	TO REMOVE AND REPLACE LEFT SIDE MIRROR ASSY.		600.00	300.00
	TO SPRAY PAINT RIGHT SIDE MIRROR COVER ASSY.	NOT NECESSARY	600.00	-
	TO CONDUCT ECU RE-PROGRAMMING AND ERASE OF FAULT CODES.		600.00	600.00
			1,800.00	900.00
GRAND TOTAL			2,683.00	1,557.00
RECOMMENDED COST OF REPAIRS				1,557.00

Report Ref No. CS/SMR22004196/Rty3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.