



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 6883Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (WCP)	BUCKLED	810.00	810.00
1	FRONT BUMPER REINFORCEMENT (WCP)	BUCKLED	280.00	280.00
1	FRONT BUMPER SPONGE (WCP)	CRACKED	95.00	95.00
1	FRONT BUMPER LH FOGLAMP COVER (WCP)	CRACKED	55.00	55.00
1	FRONT BUMPER LH FOG LAMP COVER CHROME (WCP)	SCRATCHED	45.00	45.00
1	FRONT BUMPER LH OUTER PDC SENSOR (WCP)	SERVICEABLE	115.00	-
1	FRONT BUMPER LH CORNAR PARKING SENSOR (WCP)	MISSING	115.00	115.00
1	FRONT BUMPER LH SIDE INNER FRAME (WCP)	CRACKED	55.00	55.00
12	FRONT BUMPER RIVET PIN @\$5.00 (WCP)	NECESSARY	60.00	60.00
1	SET FRONT BUMPER PDC SENSOR WIRE HARNESS (WCP)	SERVICEABLE	275.00	-
1	FRONT GRILLE ASSY (WCP)	SCRATCHED / CRACKED	520.00	520.00
1	BONNET (WCP)	BENT	1,350.00	1,350.00
1	BONNET LH UPPER LATCH (WCP)	DISTORTED	50.00	50.00
1	BONNET LH INNER LOCK (WCP)	TO REPAIR SEE LABOUR	60.00	-
2	BONNET SPRING ELEMENT @\$24.00 (WCP)	NECESSARY	48.00	48.00
1	FRONT LH FENDER (WCP)	BUCKLED	600.00	600.00
4	FRONT LH FENDER EXPANSION RIVETS @\$4.00 (WCP)	NECESSARY	16.00	16.00
1	FRT SUPPORT PANEL (WCP)	BENT	520.00	520.00
1	FRONT MOUNTING CONSOLE (WCP)	CRACKED	140.00	140.00
1	HEADLAMP LH (WCP)	BROKEN	1,720.00	1,720.00
1	HEADLAMP LH CONTROL UNIT (WCP)	SERVICEABLE	410.00	-
	COST PLUS 15%		1,100.85	971.85
			8,439.85	7,450.85
	<u>LABOUR</u>			
	REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, BONNET & ATTACHMENTS, HEADLAMP, FRT LH FENDER, FRT SUPPORT PANEL & REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BONNET LH INNER LOCK.		800.00	500.00
	PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, BONNET, FRT LH FENDER & ALL AFFECTED AREAS.		700.00	600.00

Report Ref No. CS/LPC22004201/Kny3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX PARKING SENSORS, CHECK RESET THE SAME.		80.00	60.00
	REMOVE & REFIX HEADLAMP CONTROL UNIT, REPROGRAMME & RESET THE SAME.		180.00	120.00
			1,760.00	1,280.00
GRAND TOTAL			10,199.85	8,730.85
RECOMMENDED COST OF REPAIRS				8,730.85

Report Ref No. CS/LPC22004201/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.