6/13/22, 3:16 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004204/EVY3N2

13/06/2022 Date:

REFERENCE

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00144982101

Claimant Vehicle

SNA3090Z

Insured Vehicle GBK310Z

No:

Date of Loss: 03/05/2022 Nature of Claim: TP Claim SNM22D203007/C02/TANKL

26491580125771

DESCRIPTION & IDENTIFICATION OF VEHICLE

SNA3090Z Reg No:

MERCEDES-BENZ C180, 1.5 SEDAN AVG (R17 LED) Engine No: Make & Model:

Reg. Date: 17/06/2021 (Man. Year: 2021)

W1K2050762R635441 Chassis No: Odometer: 13094 km

Colour: Grey

1497 cc **Engine Capacity:**

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50R17 225/50R17 Rear Tyre Size:

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm Front Right Side: Rear Right Side: Bridgestone 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,385.56	0.00	4,385.56	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	350.00	800.00	69.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,535.56	350.00	5,185.56	93.68
+ GST 7.00/7.00% (S\$)	387.49	24.50	362.99	93.68
Nett Amount (S\$)	5,923.05	374.50	5,548.55	93.68

INSPECTION

Date of Assignment: 06/05/2022

Accord Auto Services Pte Ltd (Bukit Merah) Date Inspected: 30/05/2022 Inspected At:

BLK 1009 BUKIT MERAH LANE 3, #01-80

Singapore 159723

Estimated Period of Repair: 2.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

6/13/22, 3:16 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jun 2022)

Parts: 143 MERCEDES-BENZ C180 1.5 SEDAN AVG (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SNA3090Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Repair	2,895.00 FL	*- FL
2	1		*REAR WINDSCREEN WITH MOULDING	Not Necessary	1,833.40 FL	*-FL
3	1		*SET CAR PLATE NUMBER WITH HOLDER	Not Necessary	50.00 FS	*-FS
4	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	4,858.40	0.00
- List Item Discount on L Items 10.00/10.00% (S\$)			472.84	0.00		
				Total Parts (S\$)	4,385.56	0.00
			Report was unsubmitted during thi	s print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	300.00	250.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECT AREA	New ED	600.00	100.00
3	TO REMOVE/REPLACE REAR WINDSCREEN	New	150.00	0.00
4	ANTI RUST TREATMENT	New	100.00	0.00
	Gros	s Labour Cost (S\$)	1,150.00	350.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >