

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004206/UTY3N2**Date:** 02/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00139332101

Claimant Vehicle No : SNC7292X **Insured Vehicle No :** SMU241G

Date of Loss: 04/05/2022 Nature of Claim: TP Claim No: SNM22D203076/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC7292X**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A) Engine No: 1ZR0H35989

Reg. Date: 11/11/2021 (Man. Year: 2021) Chassis No: MR2BE3BE300016402

Colour: Black Odometer: 13729 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,909.83	2,758.45	11,151.38	80.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	1,630.00	1,510.00	48.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,049.83	4,388.45	12,661.38	74.26
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	17,049.83	3,500.00	13,549.83	79.47

INSPECTION

Date of Assignment: 06/05/2022

Date Inspected: 09/05/2022 Inspected At: Autobay Pte Ltd (kaki Bukit) (HQ)
1 KAKI BUKIT AVE 6, #02-11
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jun 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 Elegance 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC7292X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	1,217.47 FL	*856.40 FL
2	1		*REAR BOOT RUBBER	Twisted	271.10 FL	*271.10 FL
3	1		*REAR BOOT LOCK	Serviceable	571.25 FL	*- FL
4	1		*REAR BOOT LOCK CATCH	Not Necessary	121.10 FL	*- FL
5	2		*REAR BOOT HINGE	Not Necessary	345.70 FL	*- FL
6	1		*REAR BOOT CENTRE CHROME GARNISH	Not Necessary	371.25 FL	*- FL
7	2		*REAR BOOT LH/RH CHROME GARNISH	Not Necessary	554.20 FL	*- FL
8	1		*REAR BOOT CENTRE GARNISH EMBLEM	Not Necessary	123.10 FL	*- FL
9	1		*REAR BOOT EMBLEM (COROLLA)	Necessary	121.10 FL	*82.00 FL
10	1		*REAR BOOT EMBLEM (ALTIS)	Necessary	131.75 FL	*80.00 FL
11	2		*REAR TAILLAMP	Not Necessary	1,142.20 FL	*- FL
12	2		*REAR TAILLAMP PANEL	Not Necessary	543.70 FL	*- FL
13	2		*REAR TAILLAMP GASKET	Not Necessary	242.20 FL	*- FL
14	1		*REAR END PANEL	Dented	971.10 FL	*590.30 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	371.25 FL	*288.50 FL
16	1		*REAR FLOOR PANEL	Not Necessary	1,217.10 FL	*- FL
17	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	971.10 FL	*- FL
18	2		*REAR FLOOR PANEL SIDE SPONGE	Not Necessary	542.90 FL	*- FL
19	1		*REAR BUMPER	Dented / Deformed	771.10 FL	*531.10 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	340.20 FL	*250.00 FL
21	2		*REAR BUMPER INNER BRACKET	Not Necessary	244.20 FL	*- FL
22	2		*REAR BUMPER REFLECTOR	Not Necessary	379.80 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	571.75 FL	*395.20 FL
24	2		*REAR FENDER	Not Necessary	2,434.90 FL	*- FL
25	2		*REAR FENDER SHIELD	Not Necessary	742.20 FL	*- FL
26	2		*REAR FENDER INNER GARNISH	Not Necessary	1,142.20 FL	*- FL
27	1		*REAR EXHAUST SILENCER	Not Necessary	781.10 FL	*- FL
28	1		*REAR EXHAUST RUBBER	Not Necessary	61.10 FL	*- FL
29	1		*REAR EXHAUST CHROME PIPE	Not Necessary	271.75 FL	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	289.90 FL	*- FL
31	1		*SET REAR BUMPER CLIPS	Necessary	66.00 FS	*50.00 FS
32	8		*REAR BOOT INNER TRIM BOARD CLIPS	Not Necessary	44.00 FS	*- FS
33	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
34	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	18,374.77	3,594.60
- List Item Discount on L Items 25.00/25.00% (S\$)	4,464.94	836.15
Total Parts (S\$)	13,909.83	2,758.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS,REPLACE AND ALIGN ALL PARTS	New	1,500.00	600.00
2	TO PUTTY,RE-SPRAY PAINTING AND POLISH REAR AFFECTED AREAS	New	1,300.00	900.00
3	TO RUST PROOF AFFECTED AREAS	New	100.00	60.00
4	TO CHECK AND RECTIFY WIRINGS	New	120.00	20.00
5	TO REPLACE REVERSE SENSORS AND CHECK	New	120.00	50.00
Gross Labour Cost (\$\$)			3,140.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >