

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PEQ 6382

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID	NOT NECESSARY	1,400.00	-
1	BOOTLID "PROTON" EMBLEM	NOT NECESSARY	56.00	-
1	BOOTLID "WIRA" EMBLEM	NOT NECESSARY	56.00	-
1	BOOTLID REFLECTOR PAD O/S	NOT NECESSARY	20.00	-
1	BOOTLID REFLECTOR O/S	CRACKED	155.00	155.00
1	REAR O/S FENDER	BADLY DENTED	1,088.00	867.00
1	O/S TAILLAMP	CRACKED	298.00	200.00
1	O/S TAILLAMP PANEL	BADLY DENTED	418.00	167.00
1	O/S TAILLAMP PAD	NOT NECESSARY	20.00	-
1	REAR PANEL	TO REPAIR SEE LABOUR	457.00	-
1	REAR BUMPER	BADLY DENTED	704.00	373.00
1	REAR BUMPER BEAM	NOT NECESSARY	290.00	-
	LESS 10% DISCOUNT		-	-176.20
			4,962.00	1,585.80
	SPECIAL NETT ITEMS			
1	SET REAR PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	REMOVE THE NECESSARY AFFECTED PARTS,STRAIGHTEN REAR PANEL,REAR O/S FENDER,O/S TAILLAMP PANEL AND REPLACE PARTS.		1,200.00	700.00
	PUTTY AND SPRAYPAINT.		1,400.00	600.00
	CHECK ELECTRICAL.		50.00	30.00
	TUFF KOTE.		50.00	30.00
			2,700.00	1,360.00
	GRAND TOTAL		7,712.00	2,945.80



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,350.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS3/SMR22002354/Rty3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator