

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG19016519/AEA3Q2-1**Date:** 20/06/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GBC4070G**Insured Vehicle No :** SCR6884X

Date of Loss: 31/08/2019

Nature of Claim: TP

Claim No: 2904858373SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC4070G**

Make &amp; Model: RENAULT TRAFIC, 2.0 D DCI (M)

Engine No: M9RM786C186363

Reg. Date: 26/03/2012 (Man. Year: 2011)

Chassis No: VF1FLBHB6CY424148

Colour: Black

Odometer: 306179 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16C

Rear Tyre Size: 215/65 R16C

Front Left Side: Load Star 6 mm

Rear Left Side: Load Star 6 mm

Front Right Side: Load Star 6 mm

Rear Right Side: Load Star 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,224.00	4,814.00	410.00	7.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,460.00	780.00	34.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,464.00</b>	<b>6,274.00</b>	<b>1,190.00</b>	<b>15.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>(S\$)</b>	7,464.00	5,000.00	2,464.00	33.01
<b>+ GST 7.00/7.00% (S\$)</b>	522.48	350.00	172.48	33.01
<b>Nett Amount (S\$)</b>	<b>7,986.48</b>	<b>5,350.00</b>	<b>2,636.48</b>	<b>33.01</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>(S\$)</b>		5,850.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>2,925.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,927.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,100.00</b>		

INSPECTION

Date of Assignment: 23/09/2019

Date Inspected: 23/09/2019

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT FRONT DOOR	Dented	1,350.00 FL	*1,350.00 FL
2	1		*RIGHT FRONT DOOR LOWER PROTECTOR GARNISH	Missing	350.00 FL	*350.00 FL
3	1		*RIGHT SLIDING DOOR	Dented	1,880.00 FL	*1,880.00 FL
4	1		*RIGHT SLIDING DOOR OUTER HANDLE	Cracked	390.00 FL	*390.00 FL
5	1		*RIGHT SLIDING DOOR INNER LOCK	Not Necessary	400.00 FL	*- FL
6	1		*RIGHT SLIDING DOOR WINDOW GLASS	Cut	580.00 FL	*580.00 FL
7	1		*RIGHT SLIDING DOOR WINDOW GLASS WEATHERSTRIP	Necessary	180.00 FL	*180.00 FL
8	1		*RIGHT SLIDING DOOR LOWER PROTECTOR GARNISH	Cut	350.00 FL	*350.00 FL
9	1		*RIGHT CENTRE PILLAR LOWER PROTECTOR GARNISH	Missing	180.00 FL	*180.00 FL
10	1		*RIGHT SLIDING DOOR WINDOW GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
11	1		*RIGHT FRONT DOOR CORPORATE STICKER	Necessary	50.00 FS	*30.00 FS
					Sub Total (\$)	5,790.00 5,340.00
					- List Item Discount on L Items 10.00/10.00% (\$)	566.00 526.00
					Total Parts (\$)	5,224.00 4,814.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO TRANSFER OF RIGHT FRONT DOOR AND SLIDING DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	120.00	120.00
2	TO REMOVE AND REFIT SLIDING DOOR WINDOW GLASS	New	120.00	60.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	50.00
4	TO CHECK ELECTRICAL WIRING CONCERNED	New	50.00	30.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	800.00	600.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,240.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >