

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 2609R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BRAKE DISC (CONSISTENT)	BENT	95.00	95.00
1	FRONT FORK (CONSISTENT)	BENT	180.00	180.00
1	FRONT MUDGUARD (CONSISTENT)	BROKEN	45.00	45.00
1	HANDLE BALANCER (CONSISTENT)	CUT	25.00	25.00
1	HANDLE BAR (CONSISTENT)	BENT	65.00	65.00
1	HANDLE COVER (CONSISTENT)	BROKEN	75.00	75.00
1	SET BODY (CONSISTENT)	BROKEN	380.00	380.00
1	GEAR LEVER (CONSISTENT)	BENT	45.00	45.00
1	FRONT FOOTREST (CONSISTENT)	BENT	65.00	65.00
1	MAGNET COVER (CONSISTENT)	BROKEN	110.00	110.00
1	MAGNET GASKET (CONSISTENT)	NECESSARY	8.00	8.00
1	GEAR SUB (CONSISTENT)	BENT	75.00	75.00
1	GIVI BOX (CONSISTENT)	CUT	160.00	160.00
1	REAR FORK (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT SPORT RIM (CONSISTENT)	NOT NECESSARY	220.00	-
	LESS 10% DISCOUNT		-166.80	-132.80
			1,501.20	1,195.20
	SPECIAL NETT ITEMS			
2	HELMET (SN)(CONSISTENT)	BROKEN	90.00	90.00
1	ENGINE OIL (SN)(CONSISTENT)	NECESSARY	20.00	20.00
1	IU (SN)(CONSISTENT)	сит	170.00	170.00
			280.00	280.00
	<u>LABOUR</u>			
	TRANSPORT.		40.00	40.00
	LABOR.		250.00	200.00
			290.00	240.00
	GRAND TOTAL		2,071.20	1,715.20

Report Ref No. CC4/ASM22004224/Eea3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,350.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CC4/ASM22004224/Eea3q2



Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor