



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 6140Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	DEFORMED / TORN	1,899.00	1,631.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	NOT NECESSARY	45.00	-
10	REAR BUMPER CLIPS @\$4.50 (CONSISTENT)	NECESSARY	45.00	45.00
2	REAR BUMPER CHROME MOULDING (RH/LH) @\$136.00 (CONSISTENT)	NECESSARY	272.00	272.00
1	REAR BUMPER CHEOME MOULDING (CENTER) (CONSISTENT)	NECESSARY	195.00	195.00
1	REAR LOWER ARM LH (CONSISTENT)	NOT NECESSARY	540.00	-
1	REAR KNUCKLE ARM LH (CONSISTENT)	NOT NECESSARY	1,652.00	-
1	REAR WHEEL BEARING HUP (CONSISTENT)	DAMAGED	580.00	580.00
1	REAR UPPER ARM (CONSISTENT)	NOT NECESSARY	455.00	-
1	SPORT RIM ASSY (CONSISTENT)	WARPED	960.00	960.00
	LESS 10% DISCOUNT		-664.30	-
			5,978.70	3,683.00
	<u>LABOUR</u>			
	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE & AFTER).		240.00	100.00
	TO REMOVE & REFIX REAR LH UNDERCARRIAGE. }		280.00	150.00
	TO REMOVE & REFIX REAR LH SPORT RIM & CONTACT WHEEL BEARING.}		120.00	-
	TO RESPRAY AFFECTED AREAS.		500.00	400.00
	TO RENEW DAMAGED PARTS ,STRAIGHTEN & RENEW REAR LH FENDER & ALIGNED ALL PARTS.		480.00	300.00
			1,620.00	950.00
	GRAND TOTAL		7,598.70	4,633.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00

Report Ref No. CC4/ASM22004227/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.