

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004232/APA3Q2**Date:** 01/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220007383
Claimant Vehicle No :	SGU5477G	Insured Vehicle No :	SND8529C
Date of Loss:	03/05/2022	Nature of Claim:	TP
		Claim No:	1476748821SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU5477G	Engine No:	CZC558920
Make & Model:	AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A)	Chassis No:	WAUZZZ8V6G1101952
Reg. Date:	28/10/2016 (Man. Year: 2016)	Odometer:	47753 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,915.00	97.20	8,817.80	98.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,852.00	1,952.00	900.00	31.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,767.00	2,049.20	9,717.80	82.59
+ GST 7.00/7.00% (S\$)	823.69	143.44	680.25	82.59
Nett Amount (S\$)	12,590.69	2,192.64	10,398.05	82.59
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,344.64		

INSPECTION

Date of Assignment:	18/05/2022		
Date Inspected:	18/05/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,377.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	195.00 FS	*- FS
3	1		*FRONT BUMPER TRIM COVER -RH	Not Necessary	182.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	175.00 FS	*- FS
5	4		*FRONT BUMPER PULL STRAP LOWER	Not Necessary	231.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION -RH	Not Necessary	43.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Cut	122.00 FS	*97.20 FS
8	1		*RADIATOR GRILLE	Not Necessary	765.00 FS	*- FS
9	1		*RADIATOR GRILLE COVER -UPPER	Not Necessary	109.00 FS	*- FS
10	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
11	1		*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	847.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	154.00 FS	*- FS
14	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	63.00 FS	*- FS
15	1		*RADIATOR AIR GUIDE -RH	Not Necessary	28.00 FS	*- FS
16	1		*RADIATOR AIR GUIDE -UPPER CENTER	Not Necessary	14.00 FS	*- FS
17	1		*HEADLIGHT -RH	Not Necessary	2,810.00 FS	*- FS
18	1		*LIFT CYLINDER -RH	Not Necessary	211.00 FS	*- FS
19	1		*LIFT CYLINDER HOSE -RH	Not Necessary	204.00 FS	*- FS
20	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
21	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	8,915.00 97.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,050.00	700.00
4	TO RESPRAY FRONT BUMPER	New	900.00	700.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,852.00	1,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >