

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22004249/TNY3M4**Date:** 12/10/2022**REFERENCE**

Insured/Claimant: ALAN LAM PING Policy No: DMPCSNW00215612100

Date of Loss: 29/04/2022 Nature of Claim: OD Claim No: SNM22D203025/C01/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNA9943Z**Make & Model: MERCEDES-BENZ GLB200, 1.3 PREMIUM AMG  
LINE 7-SEATER (A)

Engine No: 28291480311571

Reg. Date: 25/08/2020 (Man. Year: 2020)

Chassis No: W1N2476872W032347

Colour: White

Odometer: 34496 km

Engine Capacity: 1332 cc

Market Value/New Car Price: S\$180,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/50 R19

Rear Tyre Size: 235/50 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	30,402.20	6,054.45	24,347.75	80.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	1,460.00	2,740.00	65.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>34,602.20</b>	<b>7,514.45</b>	<b>27,087.75</b>	<b>78.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
<b>- Excess (S\$)</b>	500.00	500.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>34,102.20</b>	<b>5,500.00</b>	<b>28,602.20</b>	<b>83.87</b>

**INSPECTION**

Date of Assignment: 06/05/2022

Date Inspected: 09/05/2022 Inspected At:

BLK 10 KAKI BUKIT ROAD 2  
#01-05 FIRST EAST CENTRE, SINGAPORE  
417868

Estimated Period of Repair: 5.0 days

REPAIRER: PROFI AUTOMOTIVE

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2022)

**Parts:** M1-SUV MERCEDES-BENZ GLB200 1.3 PREMIUM AMG LINE 7-SEATER (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNA9943Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	1,449.00 FN	*- FN
2	1		*FRONT FENDER SIDE GARNISH RH	Cut	540.00 FN	*333.53 FN
3	1		*FRONT FENDER INNER SHIELD	Torn	350.00 FN	*180.00 FN
4	1		*FRONT BUMPER LOWER GARNISH	Cut	750.00 FN	*553.05 FN
5	1		*FRONT LINK ROD RH	Bent	408.00 FN	*142.95 FN
6	1		*FRONT DRIVESHAFT RH	Not Necessary	3,190.00 FN	*- FN
7	1		*FRONT STEERING KNUCKLE RH	Bent	4,856.00 FN	*1,049.91 FN
8	1		*FRONT LOWER ARM RH	Bent	1,079.00 FN	*887.45 FN
9	1		*FRONT KNUCKLE BEARING RH	Bent	422.00 FN	*422.00 FN
10	1		*FRONT SHOCK ABSORBER RH	Bent	1,842.00 FN	*872.16 FN
11	1		*STEERING RACK	Not Necessary	6,485.00 FN	*- FN
12	1		*STEERING RACK CONTROL UNIT	Not Necessary	2,820.00 FN	*- FN
13	1		*TURNING ANGLE PICK UP SENSOR RH	Not Necessary	324.00 FN	*- FN
14	1		*FRONT CROSS MEMBER	Not Necessary	5,488.00 FN	*- FN
15	1		*RIM	Cut	2,755.00 FN	*1,530.56 FN
16	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 FS	*40.00 FS
17	1		*BOTTLE BRAKE FLUID	Not Necessary	80.00 FS	*- FS
18	1		*TYRE (80%)	Cut	800.00 FS	*640.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>33,678.00</b>	<b>6,651.61</b>
<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	3,275.80	597.16
<b>Total Parts (\$\$)</b>	<b>30,402.20</b>	<b>6,054.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	100.00	0.00
2	COMPUTER DIAGNOSTIC CHECK AND CLEAR FAULT CODE	New	800.00	180.00
3	COMPUTERISED CHECK IN FRONT WHEEL ALIGNMENT	New	250.00	80.00
4	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS	New	600.00	200.00
5	REMOVE AND RENEW FRONT CROSS MEMBER	New	600.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	800.00	500.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	900.00	500.00
8	APPLY ANTI-RUST ON AFFECTED AREAS	New	150.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>4,200.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >