

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004250/ANY3Q2
Date: 20/10/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00095642201
Claimant Vehicle No :	SMN1303S	Insured Vehicle No :	SNF707Y
Date of Loss:	29/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202932/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN1303S	Engine No:	LEB5616356
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71080084
Reg. Date:	25/07/2019 (Man. Year: 2018)	Odometer:	216652 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,734.80	4,887.20	7,847.60	61.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	2,350.00	2,130.00	47.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,214.80	7,237.20	9,977.60	57.96
Approved Total (Overridden) (\$\$)		5,700.00		
Nett Amount (\$\$)	17,214.80	5,700.00	11,514.80	66.89

INSPECTION

Date of Assignment:	06/05/2022	
Date Inspected:	11/05/2022 Inspected At:	AUTO UNITED SG PTE LTD (HQ) 13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2022)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1303S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,290.00 FL	*841.00 FL
2	1		*REAR BUMPER REFLECTOR LAMP RH	Not Necessary	90.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Necessary	110.00 FL	*58.00 FL
4	1		*REAR FENDER RH	Repair	1,235.00 FL	*- FL
5	1		*REAR FENDER INNER SHIELD RH	Not Necessary	170.00 FL	*- FL
6	1		*REAR SLIDING DOOR RH	Dented	1,290.00 FL	*1,290.00 FL
7	1		*REAR SLIDING DOOR HANDLE RH	Not Necessary	105.00 FL	*- FL
8	1		*REAR SLIDING DOOR INNER TRIM BOARD RH	Cracked	980.00 FL	*750.00 FL
9	1		*REAR SLIDING DOOR MOTOR RH (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*REAR SLIDING DOOR LOCK RH	Damaged	620.00 FL	*620.00 FL
11	1		*REAR SLIDING DOOR RUBBER	Not Necessary	215.00 FL	*- FL
12	1		*REAR POWER WINDOW MOTOR	Not Necessary	984.50 FL	*- FL
13	1		*REAR ABSORBER RH	Not Necessary	410.00 FL	*- FL
14	1		*REAR AXLE	Not Necessary	1,520.00 FL	*- FL
15	1		*REAR BEARING HUB RH	Not Necessary	350.00 FL	*- FL
16	1		*FRONT FENDER RH	Dented	1,235.00 FL	*566.00 FL
17	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	170.00 FL	*- FL
18	1		*FRONT FENDER HYBRID EMBLEM	Necessary	98.90 FL	*98.90 FL
19	1		*FRONT DOOR RH	Dented	1,085.60 FL	*1,085.60 FL
20	1		*FRONT POWER WINDOW MOTOR	Damaged	984.50 FL	*387.00 FL
21	1		*LOWER SIDE SKIRT RH (NPA)	Repair	0.00 FL	*- FL
22	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
23	1		*REAR RIM COVER RH	Cut	550.00 FS	*150.00 FS
24	1		*REAR TYRE RH	Not Necessary	410.00 FS	*- FS
25	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
26	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS
27	1		*FRONT RIM COVER RH	Creased	550.00 FS	*150.00 FS
28	1		*FRONT TYRE RH	Not Necessary	410.00 FS	*- FS
29	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
30	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,323.50	6,026.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,588.70	1,139.30
Total Parts (\$\$)	12,734.80	4,887.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	2,000.00	900.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,800.00	1,200.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	180.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	150.00	60.00
5	TO REMOVE AND REPLACE UNDERCARRIAGE PART	New	200.00	80.00
6	TO CONDUCT WHEEL ALIGNMENT TEST	New	150.00	80.00
Gross Labour Cost (\$)			4,480.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >