

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004257/KQY3Q2**Date:** 05/05/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00187892101

Claimant Vehicle No : SKX5645A **Insured Vehicle No :** SMV5251P

Date of Loss: 03/05/2022 Nature of Claim: TP Claim No: SNM22D203011/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX5645A**

Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4027342

Reg. Date: 17/12/2015 (Man. Year: 2015) Chassis No: RU11107338

Colour: Metallic Maroon Odometer: 78338 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 9 mm Rear Left Side: Nexen 9 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,774.04	4,722.12	3,051.92	39.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,020.00	1,240.00	54.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,034.04	5,742.12	4,291.92	42.77
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	10,034.04	4,600.00	5,434.04	54.16
+ GST 8.00/8.00% (S\$)	802.72	368.00	434.72	54.16
Nett Amount (S\$)	10,836.76	4,968.00	5,868.76	54.16

INSPECTION

Date of Assignment: 23/09/2022

Date Inspected: 09/05/2022 Inspected At: Chew Goon Motor (AMK)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX5645A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	845.00 FL	*762.70 FL
2	14		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
3	1		*FRONT BUMPER BRACKET	Repair	29.10 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	374.00 FL	*360.80 FL
5	2		*FRONT BUMPER CORNER RETAINERS	Distorted	43.60 FL	*43.60 FL
6	1		*FRONT BUMPER FOG LAMP RH	Serviceable	327.40 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	52.00 FL	*52.00 FL
8	1		*FRONT BUMPER TOW POINT COVER	Serviceable	18.20 FL	*- FL
9	1		*FRONT BUMPER CENTER AIR GRILLE	Dented	127.00 FL	*115.60 FL
10	1		*FRONT BUMPER LOWER LIP	Mtg Cracked	295.00 FL	*295.00 FL
11	1		*GRILLE	Cracked	395.00 FL	*395.00 FL
12	2		*GRILLE SIDE BRACKETS	Cracked	100.80 FL	*100.80 FL
13	1		*GRILLE EMBLEM	Necessary	34.00 FL	*34.00 FL
14	2		*GRILLE CHROME MOULDINGS	Necessary	97.00 FL	*97.00 FL
15	1		*GRILLE TOP GARNISH COVER	Serviceable	85.40 FL	*- FL
16	2		*HEADLAMPS	Mtg Cracked	3,940.00 FL	*3,430.20 FL
17	1		*HEADLAMP LOWER BRACKET RH	Serviceable	37.00 FL	*- FL
18	1		*SUPPORT PANEL	Repair	576.20 FL	*- FL
19	1		*SUPPORT PANEL TOP CENTER BRACKET (PLASTIC)	Serviceable	45.80 FL	*- FL
20	1		*RADIATOR	Serviceable	1,291.70 FL	*- FL
21	1		*AIRCON CONDENSER	Serviceable	750.80 FL	*- FL
22	1		*AIRCON CONDENSER OUTER AIR GUIDE RH	Serviceable	36.60 FL	*- FL
23	1		*WIPER TANK	Cracked	65.00 FL	*65.00 FL
24	1		*WIPER TANK MOTOR	Dented	59.70 FL	*59.70 FL
25	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,706.30	5,891.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,932.26	1,169.28
Total Parts (\$\$)	7,774.04	4,722.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	TO REMOVE /REFIT ,RADIATOR SYSTEM ,BLEED ,REFILL COOLANT	New	160.00	0.00
3	TO REMOVE /REFIT AIR CON CONDENSER & REFILL AIR CON GAS	New	120.00	0.00
4	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF SUPPORT PANEL ,BONNET ,FRONT RH FENDER ,FRONT DOOR AND PART REPLACEMENT	New	1,100.00	400.00
5	TO RESPRAY AFFECTED AREAS	New	850.00	600.00
Gross Labour Cost (S\$)			2,260.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >