

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 3643U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	N/S REAR FENDER (WCP)	TO REPAIR SEE LABOUR	640.00	-
1	N/S REAR FENDER ARCH GARNISH (WCP)	DISTORTED	170.00	170.00
12	N/S REAR FENDER ARCH GARNISH CLIP @\$5.00 (WCP)	NECESSARY	60.00	60.00
1	N/S REAR BUMPER-SIDE (WCP)	DISTORTED	90.00	90.00
1	REAR BUMPER (WCP)	WARPED	540.00	540.00
12	REAR BUMPER CLIP @\$5.00 (WCP)	NECESSARY	60.00	60.00
1	N/S REAR BUMPER SIDE RETAINER (WCP)	CRACKED	15.00	15.00
1	N/S TAILLAMP (WCP)	CRACKED	270.00	270.00
	COST PLUS 10%		184.50	120.50
			2,029.50	1,325.50
	<u>LABOUR</u>			
	TO CHECK LIGHT SYSTEM AND WIRING.		50.00	20.00
	INSTALL REVERSE SENSOR.		120.00	50.00
	RE-SPRAY ANTI-RUST.	NOT NECESSARY	150.00	-
	APPLY BODY SEALANT TO CAR JOINTS.	NOT NECESSARY	150.00	-
	TO REMOVE INNER TRIM,GARNISH AND ETC TO FACILITATE REPAIR AND TO FIX BACK.		180.00	80.00
	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL,REPAIR INNER PANEL,REWELD INNER PANEL,REPAIR OF AND ALIGN THE SAME.INCLUSIVE OF THE REPAIR OF N/S REAR FENDER.		900.00	550.00
	TO PUTTY AND RESPRAY ACCIDENT DAMAGE AREAS.		1,100.00	600.00
			2,650.00	1,300.00
	GRAND TOTAL		4,679.50	2,625.50
	RECOMMENDED COST OF LUMP SUM REPAIRS			2.100.00

RECOMMENDED COST OF LUMP SUM REPAIRS		2,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AIS22004264/Uty3n2

CHUA KANG SENG

Licensed Appraiser