

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ALLIANZ INSURANCE SINGAPORE PTE LTD  79 ROBINSON ROAD #09-01 SINGAPORE 068897  Code: AIS  1. Policy Particulars:- THIRD PARTY CLAIM  Insured Veh. XE 4056C  Policy No.  Coverage (\$)  Code: AIS  Code: AIS  Excess (\$)  Code: AIS  Assign From SHANTI  Ref: CS/AIS220042  Policy 25/05/2022  Code: AIS  Code: AIS  ASSIGN Date  0.00  Claim No.  Ref: CS/AIS220042  Date: 25/05/2022  Code: AIS  ASSIGN Date  0.00  Code: AIS  ASSIGN Date  0.00  Claim No.  Assign Date  0.00  Claim No.  Coverage (\$)  Coverage (\$)	264/Uty3n2	
#09-01 SINGAPORE 068897  Code: AIS  1.		
1.         Policy Particulars :- THIRD PARTY CLAIM           Insured Veh.         XE 4056C         Veh. Inspected         SJZ 3643U           Policy No.         Coverage (\$)         0.00           Claim No.         800SWAISCL20220096SL         Excess (\$)         0.00		
Insured Veh.   XE 4056C   Veh. Inspected   SJZ 3643U		
Policy No.         Coverage (\$)         0.00           Claim No.         800SWAISCL20220096SL         Excess (\$)         0.00		
Claim No.         800SWAISCL20220096SL         Excess (\$)         0.00		
Assign From SHANTI Assign Date 07/05/2022		
ricoign rom		
2. Vehicle Particulars & Condition		
Make & Model HONDA HRV DX (A) c.c 1496		
Engine No. HIDDEN Year of Reg. 2016		
Chassis No. JHMRU1810GX200461 Colour RED		
Odometer102815 KMSteeringIN ORDER		
Brakes IN ORDER Modification SPORTS RIM		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre         215/60 R16         DUNLOP         6 mm		
L/H Front Tyre 215/60 R16 DUNLOP 6 mm		
R/H Rear Tyre 215/60 R16 DUNLOP 6 mm		
L/H Rear Tyre 215/60 R16 DUNLOP 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 04/05/2022 Inspection Date 09/05/2022		
Survey held at FALCON-AIR AUTO SERVICES PTE LTD		
BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days		