



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 7525L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN RUBBER	NECESSARY	271.53	271.53
1	FRONT DOOR	DAMAGED	1,295.79	1,295.79
1	FRONT DOOR CHECKER	NOT NECESSARY	131.75	-
1	FRONT DOOR GLASS	DAMAGED	489.50	408.00
1	FRONT DOOR GLASS OUTER MOULDING	DAMAGED	133.95	133.95
1	FRONT DOOR CHANNEL	NECESSARY	149.50	149.50
2	FRONT DOOR HINGES	INTACT	78.50	-
1	FRONT DOOR RUBBER	NECESSARY	190.05	190.05
1	FRONT SIDE ROUND MIRROR	DAMAGED	105.80	105.80
1	FRONT MIRROR STAY	DAMAGED	305.10	305.10
1	FRONT SIDE MIRROR	DAMAGED	286.95	286.95
1	FRONT DOOR PILLAR	DAMAGED	711.50	485.00
1	FRONT DOOR PILLAR FRAME RUBBER	NOT NECESSARY	149.65	-
	LESS 25% DISCOUNT		-1,074.89	-907.92
			3,224.68	2,723.75
LABOUR				
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS.		50.00	30.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIR.		120.00	50.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		900.00	600.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		900.00	400.00

Report Ref No. CS3/LPC22002182/Eqy3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	30.00
			2,320.00	1,230.00
GRAND TOTAL			5,544.68	3,953.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,150.00

Report Ref No. CS3/LPC22002182/Eqy3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.