

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004276/APA3Q2**Date:** 29/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210025047
Claimant Vehicle No :	YN9773Z	Insured Vehicle No :	SDQ1018G
Date of Loss:	05/05/2022	Nature of Claim:	TP
		Claim No:	6491405193SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN9773Z		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10B84184
Reg. Date:	26/10/2015 (Man. Year: 2015)	Chassis No:	FEB21EA10555
Colour:	White	Odometer:	193139 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,646.30	16,581.15	12,065.15	42.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,600.00	2,940.00	2,660.00	47.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,246.30	19,521.15	14,725.15	43.00
Approved Total (Overridden) (S\$)		15,600.00		
Nett Amount (S\$)	34,246.30	15,600.00	18,646.30	54.45
+ Car Rental (12.0 x S\$150.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		17,407.45		
Global Sum Settlement (S\$)		17,400.00		

INSPECTION

Date of Assignment:	09/05/2022	
Date Inspected:	09/05/2022 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,021.90 F	*1,021.90 FL
2	1		*FRONT BUMPER SIDE GARNISH	O/S Cut	789.80 F	*394.90 FL
3	1		*FRONT GRILLE	Cracked	1,458.30 F	*950.00 FL
4	1		*FRONT GRILLE CENTRE EMBLEM	Necessary	85.80 F	*85.80 FL
5	1		*SET FRONT GRILLE CLIPS	Necessary	60.00 F	*30.00 FL
6	2		*FRONT CORNER PANEL	Cracked	1,260.00 F	*959.00 FL
7	2		*FRONT HEADLAMP	Cracked	1,117.60 F	*1,117.60 FL
8	2		*FRONT HEADLAMP SIDE GARNISH	Cracked	789.80 F	*190.00 FL
9	2		*FRONT HEADLAMP LOWER RUBBER (NPA)	Not Necessary	0.00 F	*- FL
10	2		*FRONT SIDE LAMP	Cracked	594.00 F	*594.00 FL
11	1		*FRONT LH SIDE MIRROR TOP COVER	Not Necessary	34.00 F	*- FL
12	1		*FRONT LH SIDE MIRROR TOP GARNISH	Not Necessary	34.10 F	*- FL
13	1		*FRONT RH DOOR	Dented	2,200.00 F	*1,910.00 FL
14	1		*FRONT RH DOOR TOP HINGE	Not Necessary	178.20 F	*- FL
15	1		*FRONT RH DOOR LOWER HINGE	Not Necessary	178.20 F	*- FL
16	1		*FRONT RH DOOR STOPPER	Not Necessary	94.60 F	*- FL
17	1		*FRONT STEP PANEL	Deformed	750.00 F	*415.00 FL
18	1		*FRONT RH ARCH PANEL GARNISH (NPA)	Not Necessary	0.00 F	*- FL
19	1		*SLIDING DOOR LH	Distorted	2,500.00 FS	*2,000.00 FS
20	1		*SLIDING DOOR LOCK LH	Not Necessary	200.00 FS	*- FS
21	1		*SLIDING DOOR FRONT PILLAR LH	Distorted	1,400.00 FS	*950.00 FS
22	1		*SLIDING DOOR LOWER FRAME LH	Dented	1,200.00 FS	*800.00 FS
23	1		*SLIDING DOOR LOWER STEP PANEL LH	Bent	400.00 FS	*280.00 FS
24	1		*SLIDING DOOR LOWER PROTECTION BEAM LH	Bent	800.00 FS	*500.00 FS
25	2		*SLIDING DOOR LOWER PROTECTION BEAM BRACKET LH	Bent	500.00 FS	*200.00 FS
26	1		*REAR STORAGE BOX BODY PANEL LH	Dented	2,500.00 FS	*2,000.00 FS
27	1		*REAR STORAGE BOX BODY PANEL PILLAR LH	Not Necessary	1,000.00 FS	*- FS
28	1		*U BOLTS (6 PCS)	Bent (4 PCS ONLY)	900.00 FS	*400.00 FS
29	1		*REAR STORAGE BOX HORIZONTAL WOODEN BEAM (6 PCS)	Damaged (5 PCS ONLY)	4,800.00 FS	*2,500.00 FS
30	1		*ADVERTISEMENT STICKERS	Necessary	1,800.00 FS	*1,200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 28,646.30 18,498.20
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,917.05

Total Parts (\$\$) 28,646.30 16,581.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	800.00
2	SPRAY PAINTING	New	2,000.00	1,000.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
6	TO VARNISH WOODEN BEAMS	New	400.00	300.00
7	TO LIFT UP REAR STOGAGE BOX	New	800.00	650.00
Gross Labour Cost (S\$)			5,600.00	2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >