

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004280/UA3Q2**Date:** 04/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900168332
Claimant Vehicle No :	GBH9764D	Insured Vehicle No :	SMP6059D
Date of Loss:	07/05/2022	Nature of Claim:	TP
		Claim No:	4491429886SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH9764D		
Make & Model:	TOYOTA PROACE COMFORT MEDIUM, 2.0 (M)	Engine No:	AH014011640
Reg. Date:	14/11/2018 (Man. Year: 2016)	Chassis No:	YARVFAHKHGZ069474
Colour:	Silver	Odometer:	118534 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R16	Rear Tyre Size:	215/65 R16
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,422.05	6,122.70	1,299.35	17.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,925.00	2,655.00	1,270.00	32.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,347.05	8,777.70	2,569.35	22.64
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	11,347.05	7,000.00	4,347.05	38.31
+ GST 7.00/7.00% (S\$)	794.29	490.00	304.29	38.31
Nett Amount (S\$)	12,141.34	7,490.00	4,651.34	38.31
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		8,090.00		

INSPECTION

Date of Assignment:	09/05/2022	
Date Inspected:	09/05/2022	Inspected At: NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** HOW MEI KWAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Badly Dented	1,955.80 FL	*1,880.00 FL
2	1		*REAR DOOR HINGE BOTTOM	Bent	218.50 FL	*218.50 FL
3	1		*REAR DOOR HINGE TOP	Not Necessary	218.50 FL	*- FL
4	1		*REAR DOOR INNER WOOD BOARD	Not Necessary	325.60 FL	*- FL
5	9		*REAR DOOR INNER WOOD BOARD CLIPS	Not Necessary	45.00 FL	*- FL
6	1		*REAR BOOT EMBLEM	Necessary	145.80 FL	*145.80 FL
7	1		*REAR BOOT LOCK LOWER	Not Necessary	182.90 FL	*- FL
8	1		*REAR LAMP ASSY RH	Cracked	385.50 FL	*385.50 FL
9	1		*REAR BOOT RUBBER	Not Necessary	295.30 FL	*- FL
10	1		*REAR BUMPER	Distorted	792.20 FL	*792.20 FL
11	1		*REAR BUMPER SIDE RETAINER RH	Cracked	155.50 FL	*155.50 FL
12	1		*REAR BUMPER REFLECTOR LAMP RH	Cracked	142.30 FL	*142.30 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	688.40 FL	*688.40 FL
14	1		*REAR LAMP ROCKER PANEL OUTER RH	Dented	385.20 FL	*385.20 FL
15	1		*REAR BUMPER INNER END PANEL	No such part	582.70 FL	*- FL
16	1		*REAR FENDER RH	Badly Dented / Buckled	1,958.50 FL	*1,958.50 FL
17	1		*REAR FENDER AIR SCOOP GRILLE	Distorted	195.40 FL	*195.40 FL
18	1		*REAR FENDER INNER COWLING RH	Torn	238.60 FL	*238.60 FL
19	8		*REAR FENDER INNER COWLING CLIPS	Necessary	40.00 FL	*40.00 FL
20	1		*REAR BUMPER LOWER COWLING JOINT RH	Twisted	128.80 FL	*128.80 FL
21	1		*REAR LAMP ROCKER PANEL	Dented	488.90 FL	*488.90 FL
22	1		*REAR WINDSCREEN SEALANT	Necessary	45.00 FS	*40.00 FS
23	1		*SET REAR BUMPER PARKING SENSOR	Shorted	200.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	9,814.40 8,083.60
- List Item Discount on L Items 25.00/25.00% (\$\$)					2,392.35	1,960.90
					Total Parts (\$\$)	7,422.05 6,122.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL REAR WINDSCREEN	New	100.00	100.00
2	REMOVE & INSTALL R/LAMP ,R/DOOR,R/BUMPER,BUMPER REINFORCEMENT ,CUT OUT & RENEW R/LAMP PANEL ,BUMPER LOWER ROKCER PANEL ,R/FENDER RH,KNOCK R/FENDER INNER PANEL,FLOORBOARD PANEL AND RESTRAIGHTEN BODY & CHASSIS	New	1,800.00	1,400.00
3	CAR O-LINER	New	350.00	0.00
4	CHECK WIRING SYSTEM	New	25.00	25.00
5	RENEW PARKING SENSOR	New	80.00	50.00
6	SPRAY PAINTING	New	1,300.00	1,000.00
7	REMOVE & INSTALL R/FINISHER AND BOARD	New	150.00	80.00
8	TOWING FEE WITH LAMP	New	120.00	0.00
Gross Labour Cost (\$\$)			3,925.00	2,655.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >