

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22004294/VNY3E2

**Date:** 08/07/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00087472100  
Claimant Vehicle No : SKR1223S Insured Vehicle No : SMY9754M  
Date of Loss: 04/05/2022 Nature of Claim: TP Claim No: SNM22D203051/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR1223S**  
Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN254273  
Reg. Date: 12/04/2012 (Man. Year: 2012) Chassis No: WAUZZZ4G2CN119892  
Colour: White Odometer: 167605 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/35Z R20 Rear Tyre Size: 255/35 ZR20  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,217.59	8,131.84	2,085.75	20.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,440.00	1,270.00	46.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,927.59</b>	<b>9,571.84</b>	<b>3,355.75</b>	<b>25.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,650.00</b>		
<b>(S\$)</b>	12,927.59	7,650.00	5,277.59	40.82
<b>+ GST 7.00/7.00% (S\$)</b>	904.93	535.50	369.43	40.82
<b>Nett Amount (S\$)</b>	<b>13,832.52</b>	<b>8,185.50</b>	<b>5,647.02</b>	<b>40.82</b>

### INSPECTION

Date of Assignment: 09/05/2022  
Date Inspected: 11/05/2022 Inspected At: Teamwork Garage Pte Ltd (HQ)  
53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park  
Singapore 408934  
Estimated Period of Repair: 5.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2022)
Parts:	143	AUDI A6 2.0 TFSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1223S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	2,058.54 FL	*2,058.54 FL
2	1		*REAR BUMPER LOWER GARNISH	Cut	282.84 FL	*282.84 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	774.40 FL	*774.40 FL
4	1		*REAR BUMPER RETAINER (2PCS)	Necessary	82.83 FL	*82.83 FL
5	1		*REAR BUMPER TOP BRACKET	Necessary	89.54 FL	*89.54 FL
6	1		*REAR BUMPER TOW COVER	Missing	47.61 FL	*47.61 FL
7	1		*REAR BUMPER PDC SENSOR (2PCS)	Cut (1PC Only)	480.36 FL	*225.00 FL
8	1		*EXHAUST SILENCER	Dented	1,285.98 FL	*1,285.98 FL
9	2		*EXHAUST SILENCER MOUNTING	Serviceable	139.26 FL	*- FL
10	1		*BOOTLID	Dented	2,314.34 FL	*1,940.00 FL
11	1		*BOOTLID EMBLEM - LOGO	Necessary	103.02 FL	*103.02 FL
12	1		*BOOTLID EMBLEM - S6	Necessary	106.32 FL	*106.32 FL
13	1		*BOOTLID WEATHERSTRIP	Serviceable	163.63 FL	*- FL
14	1		*BOOTLID LAMP RH	Cracked	964.30 FL	*850.00 FL
15	1		*TAILLAMP RH	Cracked	1,034.94 FL	*900.00 FL
16	1		*TAILLAMP BRACKET RH	Necessary	45.37 FL	*45.37 FL
17	1		*END PANEL	Repair	884.35 FL	*- FL
18	1		*END PANEL TOP GARNISH	Serviceable	95.76 FL	*- FL
19	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
21	1		*REAR SMART SENSOR OPENER	Bent	210.60 FL	*210.60 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	11,333.99 9,032.05
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,116.40 900.21
					Total Parts (\$\$)	10,217.59 8,131.84

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE, RENEW AND REFIT REVERSE SENSOR	New	150.00	30.00
2	REMOVE TRIMS & GARNISHES TO FACILITATE REPAIR	New	150.00	50.00
3	REMOVE & REFIT REAR EXHAUST SILENCER	New	200.00	100.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	600.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
7	CHECK WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,710.00</b>	<b>1,440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >