

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22004295/ETY3E2

Date: 14/06/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00007322200
Claimant Vehicle No : SNE1552A **Insured Vehicle No :** PC9130T
Date of Loss: 06/05/2022 Nature of Claim: TP Claim No: SNM22D203135/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE1552A**
Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15ZK1100068
Reg. Date: 23/02/2022 (Man. Year: 2021) Chassis No: JHMRV3800NS200068
Colour: White Odometer: 6936 km
Engine Capacity: 1498 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,458.61	2,620.44	838.17	24.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,240.00	5,880.00	4,360.00	42.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,698.61	8,500.44	5,198.17	37.95
+ GST 7.00/7.00% (S\$)	958.90	595.03	363.87	37.95
Nett Amount (S\$)	14,657.51	9,095.47	5,562.04	37.95

INSPECTION

Date of Assignment: 09/05/2022
Date Inspected: 23/05/2022 Inspected At: Kah Motor Co Sdn Bhd (ALEXANDRA)
255 ALEXANDRA ROAD
Singapore 159937
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2022)
Parts:	M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE1552A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Dented	687.52 FS	*687.52 FS
2	1		*CLIPTAILGATE SPOILER (9PCS)	Necessary	17.55 FS	*17.55 FS
3	1		*EMBLEM SET.RR.	Necessary	26.77 FS	*26.77 FS
4	1		*LIGHT ASSY,R.LID	Broken	347.25 FS	*347.25 FS
5	1		*LIGHT ASSY,R.TAIL	Not Necessary	328.12 FS	*- FS
6	1		*FACE,RR.BUMPER	Broken	423.15 FS	*423.15 FS
7	1		*FACE ASSY RR BPR	Crushed	366.22 FS	*366.22 FS
8	1		*SPACER,R.RR.BPR S	Necessary	14.25 FS	*14.25 FS
9	1		*SPACER,L.RR.BPR S	Necessary	14.25 FS	*14.25 FS
10	1		*CLIP,BUMPER (6PCS)	Necessary	10.35 FS	*10.35 FS
11	1		*PROTECTOR, R.RR.W	Not Necessary	72.90 FS	*- FS
12	1		*PANEL COMP, REAR	Not Necessary	387.15 FS	*- FS
13	1		*RUBBER,R.W/SHLD DA	Necessary	9.52 FS	*9.52 FS
14	1		*RUBBER,WSHLD DAM	Necessary	19.95 FS	*19.95 FS
15	1		*SPACER.RR.WINDSHIELD (2PCS)	Necessary	4.35 FS	*4.35 FS
16	1		*DAMPERSTD 5X5	Necessary	6.82 FS	*6.82 FS
17	1		*RUBBER,L.WSHLD DA	Necessary	9.52 FS	*9.52 FS
18	1		*CLIP,RR.WINDSHIELD LOWER (2PCS)	Necessary	6.45 FS	*6.45 FS
19	1		*CLIP,RR.WINDSHIELD UPPER (2PCS)	Necessary	4.35 FS	*4.35 FS
20	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
21	1		*GARNISH ASSY,TAILGATE LOWER	Broken	530.17 FS	*530.17 FS
22	4		*SENSOR RETAINER	Necessary	72.00 FS	*72.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **3,458.61** **2,620.44**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	280.00	280.00
2	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	New	650.00	650.00
3	REPLACE RR.WINDSCREEN	New	650.00	650.00
4	REMOVE & RENEW REVERSE SENSORS - 4 PCS	New	280.00	280.00
5	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	480.00
6	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	560.00	480.00
7	WINDSCREEN DAM KIT	New	120.00	100.00
8	BODY JOINT SEALANT TAILGATE	New	120.00	100.00
9	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	3,900.00	1,300.00
10	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	New	3,120.00	1,560.00
Gross Labour Cost (\$\$)			10,240.00	5,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >