

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

HL Assurance Pte Ltd
11 Keppel Road, #11-01 ABI Plaza
Singapore 089057

Our File No: CS/HLA22004303/UTY3E2

Date: 06/06/2022

REFERENCE

Insured/Claimant: FELIX OOI AIK SIONG Policy No: MP316865
Date of Loss: 05/05/2022 Nature of Claim: OD Claim No: MPC03390

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL8364S**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRX591005
Reg. Date: 13/03/2017 (Man. Year: 2016) Chassis No: MR053REH104556857
Colour: Silver Odometer: 78900 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,123.90	3,128.40	995.50	24.14
Miscellaneous Items	125.00	75.00	50.00	40.00
Labour	1,530.00	1,160.00	370.00	24.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,778.90	4,363.40	1,415.50	24.49
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	5,778.90	3,763.40	2,015.50	34.88
+ GST 7.00/7.00% (S\$)	404.52	263.44	141.08	34.88
Nett Amount (S\$)	6,183.42	4,026.84	2,156.58	34.88

INSPECTION

Date of Assignment: 09/05/2022 Present Location: SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 10/05/2022 Inspected At: SME Motor Pte Ltd (Kaki Bukit)
1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Jun 2022)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL8364S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Bent / Buckled	380.00 F	*380.00 F
2	1		*FRT BONNET LOCK (WCP)	Twisted	65.00 F	*65.00 F
3	2		*FRT BONNET HINGE (WCP)	Repair	90.00 F	*- F
4	10		*FRT BONNET INSULATOR CLIP (WCP)	Not Necessary	20.00 F	*- F
5	1		*FRT GRILLE (WCP)	Cracked	195.00 F	*195.00 F
6	4		*FRT GRILLE CLIP (WCP)	Necessary	8.00 F	*8.00 F
7	1		*FRT GRILLE TOP GARNISH (WCP)	Not Necessary	65.00 F	*- F
8	1		*FRT BUMPER (WCP)	Torn	235.00 F	*235.00 F
9	2		*FRT BUMPER RETAINER (WCP)	Necessary	76.00 F	*76.00 F
10	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
11	1		*FRT BUMPER INNER SPONGE (WCP)	Not Necessary	75.00 F	*- F
12	1		*FRT BUMPER REINFORCEMENT (WCP)	Repair	175.00 F	*- F
13	2		*HEADLAMP (WCP)	Holder Cracked	1,460.00 F	*1,460.00 F
14	1		*BRACE PANEL (WCP)	Bent	55.00 F	*55.00 F
15	1		*AIRCON CONDENSER (WCP)	Bent / Punctured	350.00 F	*350.00 F
16	1		*RADIATOR (WCP)	Serviceable	480.00 F	*- F

F=Franchise part.

Sub Total (S\$)	3,749.00	2,844.00
+ Margin on L,N Items 10.00/10.00% (S\$)	374.90	284.40
Total Parts (S\$)	4,123.90	3,128.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT BONNET SEALANT (NECESSARY)	60.00	40.00
2	1	FRT NUMBER PLATE (BENT)	40.00	35.00
3	1	RADIATOR COOLANT (NOT NECESSARY)	25.00	0.00
			Sub Total (\$\$)	125.00
				75.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	LABOUR CHARGE	New	700.00	500.00
4	SPRAY PAINTING	New	700.00	540.00
			Gross Labour Cost (\$\$)	1,530.00
				1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >