

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004311/EVY3Q2**Date:** 30/05/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00105922101

Claimant Vehicle No : SMS3139K**Insured Vehicle No :** XE5840Z

Date of Loss: 31/03/2022

Nature of Claim: TP

Claim No: SNM22D202236/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMS3139K**

Make & Model: KIA CERATO, 1.6 (A)

Reg. Date: 21/02/2020 (Man. Year: 2019)

Colour: Grey

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G4FGKH739896

Chassis No: KNAF3416ML5060250

Odometer: 60095 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16

Front Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size: 195/55 R16

Rear Left Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,003.00	2,492.00	6,511.00	72.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	2,910.00	3,340.00	53.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,253.00	5,402.00	9,851.00	64.58
+ GST 7.00/7.00% (S\$)	1,067.71	378.14	689.57	64.58
Nett Amount (S\$)	16,320.71	5,780.14	10,540.57	64.58

INSPECTION

Date of Assignment: 27/05/2022

Date Inspected: 10/05/2022 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS3139K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
2	1		*REVERSE SENSOR	Shorted	220.00 FS	*220.00 FS
3	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
4	1		*COVER -RR BUMPER	Dented	651.00 FS	*651.00 FS
5	1		*COVER -RR BUMPER LWR	Not Necessary	241.00 FS	*- FS
6	1		*COVER -RR BUMPER FOG LAMP ,LH	Not Necessary	19.00 FS	*- FS
7	1		*COVER -RR BUMPER FOG LAMP ,RH	Not Necessary	19.00 FS	*- FS
8	1		*LAMP ASSY -SIDE T/SIGNAL ,LH	Not Necessary	201.00 FS	*- FS
9	1		*LAMP ASSY -SIDE T/SIGNAL ,RH	Not Necessary	201.00 FS	*- FS
10	1		*EXIN WIRING ASSY -BWS	Not Necessary	207.00 FS	*- FS
11	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
12	1		*STAY -RR BUMPER LH	Not Necessary	65.00 FS	*- FS
13	1		*STAY -RR BUMPER RH	Not Necessary	65.00 FS	*- FS
14	1		*BRACKET ASSY -RR BPR SIDE UPR ,L	Not Necessary	25.00 FS	*- FS
15	1		*BRACKET ASSY -RR BPR SIDE UPR ,R	Not Necessary	31.00 FS	*- FS
16	1		*PANEL ASSY -TRUNK LID	Dented	1,491.00 FS	*1,491.00 FS
17	1		*LATCH ASSY -TRUNK LID	Not Necessary	112.00 FS	*- FS
18	1		*LOGO ASSY -KIA SUB	Necessary	32.00 FS	*32.00 FS
19	1		*EMBLEM -CERATO	Necessary	28.00 FS	*28.00 FS
20	1		*LAMP ASSY ,CENTER GARNISH	Not Necessary	690.00 FS	*- FS
21	1		*LAMP ASSY -REAR COMB OUTSIDE ,LH	Not Necessary	675.00 FS	*- FS
22	1		*LAMP ASSY -REAR COMB OUTSIDE ,RH	Not Necessary	675.00 FS	*- FS
23	1		*LAMP ASSY -REAR COMB INSIDE,LH	Not Necessary	608.00 FS	*- FS
24	1		*LAMP ASSY -REAR COMB INSIDE,RH	Not Necessary	608.00 FS	*- FS
25	1		*NEW K3 2020 STEEL GRAY KLG	Not Necessary	1,721.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					9,003.00	2,492.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW RR BUMPER ,RR BUMPER BODY KIT & BOOTLID REPAIR RR END PNL	New	3,200.00	1,280.00
2	RESPRAY RR BUMPER ,RR BUMPER BODY KIT ,BOOTLID & RR END PNL	New	2,200.00	1,100.00
3	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET TO FACILITATE REPAIR	New	150.00	0.00
4	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	280.00	280.00
6	SUPPLY RR BUMPER PLATE WITH CASING	New	80.00	0.00
7	REMOVE & REFIT REVERSE SENSOR	New	100.00	100.00
8	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	30.00
9	SUPPLY BODY PNL SEALANT	New	80.00	40.00
Gross Labour Cost (\$)			6,250.00	2,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >