## **BIS AUTOMOBILES**

30 Teban Gardens Crescent Singapore 608927 BIS Automobiles Pte Ltd Co. Reg. No. 201908617D. GST Reg. No. 201908617D

## **FINAL REPORT**

Estimate No. : 21998908

Date Estimated : 07/05/2022

Prepared By : Gary Poh Chai Hoon

- ESTIMATE REPAIR FOR -

Mr. Ng Shou Chuan China Taiping Insurance (S) Pte Ltd

3 Anson Road

- ACCOUNT -

#16-00 Springleaf Tower

Singapore 079909

Motor Claims Department

REGN. NO.	CHASSIS NO.	REGN.DATE	MODEL
SJN5189P	W203001992	19/2/2009	TOYOTA WISH

DESCRIPTION	ORIGINAL	PRICE DISC	. %	NETT
· · · · · · · · · · · · · · · · · · ·	•			1,050.00 🗸
To spray paint rear bumper, tail end panel and boot lid				1,050.00 🗸
To transfer PDC assembly from old to new bumper incresetting and conducting checks for proper function	lude			50.00 🗸
To remove and install Rear windscreen glass to facilitat repairs including water leak tests	е		150	✓ 5 <del>76.</del> 00
			80 \	✓ 3 <del>60.</del> 00
, ,			NN	50.00
Sundries		2410		30.00 🗸
DESCRIPTION	UNIT PRICE	QTY DISC	. %	NETT
Bumper retainer, rear left Bumper retainer, rear right Trunk lid Rear bumper cover Repair Kit windscreen (supp) Bulb longlife 5W (supp)	70 \left\( \)16\frac{1.0}{0} \\ 70 \left\( \) 16\frac{1.0}{0} \\ 1239.35 \left\( \) 570 \left\( \) 103\frac{5.0}{0} \\ 131.55 \left\( \) 10.85 \left\( \)	1.00 1.00 1.00 2.00	5.00 5.00 5.00 5.00	152.95 152.95 1177.39 983.25 249.95 10.31
	To replace rear bumper and attachments, tail end pane boot lid include knocking out dents caused by the accided to spray paint rear bumper, tail end panel and boot lided. To transfer PDC assembly from old to new bumper incresetting and conducting checks for proper function. To remove and install Rear windscreen glass to facilitate repairs including water leak tests.  To transfer lock mechanism from old to new boot lide inconducting checks on all doors sensor and central lock system for proper function.  To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function.  Sundries  DESCRIPTION  Bumper retainer, rear left Bumper retainer, rear right Trunk lid Rear bumper cover Repair Kit windscreen (supp)	To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident  To spray paint rear bumper, tail end panel and boot lid  To transfer PDC assembly from old to new bumper include resetting and conducting checks for proper function  To remove and install Rear windscreen glass to facilitate repairs including water leak tests  To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function  To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function  Sundries  DESCRIPTION  UNIT PRICE  Bumper retainer, rear left  70 164.00  Trunk lid  1239.35 </19 Rear bumper cover  570 1035.00  Repair Kit windscreen (supp)</td <td>To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident  To spray paint rear bumper, tail end panel and boot lid  To transfer PDC assembly from old to new bumper include resetting and conducting checks for proper function  To remove and install Rear windscreen glass to facilitate repairs including water leak tests  To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function  To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function  Sundries  2410  DESCRIPTION  UNIT PRICE  QTY DISCRIPTION  Bumper retainer, rear left  70 &lt; 164-90 1.00  Bumper retainer, rear right  70 &lt; 164-90 1.00  Trunk lid 1239.35 &lt; 1.00  Rear bumper cover  570 &lt; 1035-00 1.00  Repair Kit windscreen (supp)</td> <td>To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident  To spray paint rear bumper, tail end panel and boot lid  To transfer PDC assembly from old to new bumper include resetting and conducting checks for proper function  To remove and install Rear windscreen glass to facilitate repairs including water leak tests  To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function  To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function  Sundries  DESCRIPTION  UNIT PRICE  QTY DISC. %  Bumper retainer, rear left  70 \( 161-90 \) 1.00 5.00  Bumper retainer, rear right  70 \( 161-90 \) 1.00 5.00  Trunk lid  1239.35 \( 1.00 \) 5.00  Rear bumper cover  570 \( 103-5.00 \) 1.00 5.00  Repair Kit windscreen (supp)</td>	To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident  To spray paint rear bumper, tail end panel and boot lid  To transfer PDC assembly from old to new bumper include resetting and conducting checks for proper function  To remove and install Rear windscreen glass to facilitate repairs including water leak tests  To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function  To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function  Sundries  2410  DESCRIPTION  UNIT PRICE  QTY DISCRIPTION  Bumper retainer, rear left  70 < 164-90 1.00  Bumper retainer, rear right  70 < 164-90 1.00  Trunk lid 1239.35 < 1.00  Rear bumper cover  570 < 1035-00 1.00  Repair Kit windscreen (supp)	To replace rear bumper and attachments, tail end panel, boot lid include knocking out dents caused by the accident  To spray paint rear bumper, tail end panel and boot lid  To transfer PDC assembly from old to new bumper include resetting and conducting checks for proper function  To remove and install Rear windscreen glass to facilitate repairs including water leak tests  To transfer lock mechanism from old to new boot lid include conducting checks on all doors sensor and central locking system for proper function  To reconnect all electrical components and wirings at the Rear section include conducting checks for proper function  Sundries  DESCRIPTION  UNIT PRICE  QTY DISC. %  Bumper retainer, rear left  70 \( 161-90 \) 1.00 5.00  Bumper retainer, rear right  70 \( 161-90 \) 1.00 5.00  Trunk lid  1239.35 \( 1.00 \) 5.00  Rear bumper cover  570 \( 103-5.00 \) 1.00 5.00  Repair Kit windscreen (supp)

2091.75 -20% 1673.40

P/P - 4083.40

6 DAYS

 Total Labour :
 3,166.00

 Total Parts :
 2,726.80

 Total Labour & Parts :
 5,892.80

 Deduction for Excess :
 5,892.80

 Total Repair Costs less Excess:
 5,892.80

 GST @7%:
 412.50

 Grand Total :
 6,305.30