

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22004321/Rqy3e2
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	26/05/2022
	ATTN : KHONG LY	NN		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SJU 9085S	Veh. Inspected		SJL 3286R
	Policy No.	GA562223	Coverage (\$)		0.00
	Claim No.	S2M040F1	Excess (\$)		0.00
	Assign From	KHONG LYNN	Assign Date		09/05/2022
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI / LANCER 1.6 A	c.c		1584
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	JMYSTCS3A8U010555	Colour		GREY
	Odometer	208608 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/55R15	KUMHO		6 mm
	L/H Front Tyre	195/55R15	KUMHO		6 mm
	R/H Rear Tyre	195/55R15	KUMHO		6 mm
	L/H Rear Tyre	195/55R15	KUMHO		6 mm
4. Description of Damages					
	THE VEHICLE SUS	EHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
5.	General Information				
	Accident Date	07/05/2022	Inspect Date /	Time	17/05/2022 ( 04:12 PM )
	Survey held at	BLK 7 SIN MING IND EST SECT	OR C #01-82 S57	5642	
	Repairer	GUAN AUTO SERVICE			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/ASM22004321/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser