

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004332/ENY3Q2**Date:** 05/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00083922200		
Claimant Vehicle No :	PA5722Y	Insured Vehicle No :	SKF8987M		
Date of Loss:	09/05/2022	Nature of Claim:	TP	Claim No:	SNM22D203141/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PA5722Y		Engine No:	6HH1328183
Make & Model:	ISUZU LT133P, 8.2 D (M)		Chassis No:	JALLT133P57000030
Reg. Date:	24/10/2005 (Man. Year: 2005)		Odometer:	902592 km
Colour:	Multi-colour			
Engine Capacity:	8226 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,485.00	1,735.00	1,750.00	50.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,500.00	400.00	21.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,385.00	3,235.00	2,150.00	39.93
+ GST 8.00/8.00% (S\$)	430.80	258.80	172.00	39.93
Nett Amount (S\$)	5,815.80	3,493.80	2,322.00	39.93

INSPECTION

Date of Assignment:	10/05/2022		
Date Inspected:	10/05/2022	Inspected At:	Connect3 (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jul 2023)	
Parts:	N/A	ISUZU LT133P 8.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA5722Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER (LH)	Broken	1,750.00 F	*1,550.00 F	
2	1		*REAR LH LAST COMPARTMENT COVER PANEL	Repair	1,550.00 F	*- F	
3	1		*REAR LH LAST COMPARTMENT COVER OUTER LOCK	Bent	185.00 F	*185.00 F	
					Total Parts (S\$)	3,485.00	1,735.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	900.00	600.00
2	SPRAY PAINTING WITH DESIGNS	New	1,000.00	900.00
			Gross Labour Cost (S\$)	1,900.00
				1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >