

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1668L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FENDER ASM-FRT-LH (DISC 10%)	BENT	379.80	341.82
1	FASCIA-FR BPR (DISC 10%)	SCRATCHED	721.66	649.49
1	PANEL-BODY SI OTR FRT-LH	NOT NECESSARY	235.24	-
1	PANEL-BODY SI OTR MID	NOT NECESSARY	323.23	-
1	DOOR ASM-RR SI-L	NOT NECESSARY	2,185.04	-
1	DOOR ASM-FRT SI-L	NOT NECESSARY	2,338.76	-
1	STICKER STRIDES TAXI (DOOR)	NOT NECESSARY	60.00	-
1	FASCIA-RR BPR	NOT NECESSARY	758.47	-
1	STICKER ELECTRIC (LOGO)	NOT NECESSARY	21.60	-
1	SENSOR-RR PARK DIST CONT	NOT NECESSARY	65.00	-
1	MIRROR ASM-O/S RR VIEW-LH	NOT NECESSARY	478.40	-
1	WHEEL	NOT NECESSARY	618.07	-
1	BEARING ASM-RR WHL	NOT NECESSARY	335.40	-
1	PANEL-BODY SI OTR RR FENDER-LH	TO REPAIR SEE LABOUR	1,201.52	-
			9,722.19	991.31
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF PANEL-BODY SI OTR RR FENDER-LH.		1,800.00	500.00
	SPRAY PAINT.		3,258.00	600.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	40.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO CHECK & RESET SYSTEM FUNCTION.	NOT NECESSARY	350.00	-
	TO DO WHEEL ALIGNMENT/TYRE BALANCING.	NOT NECESSARY	120.00	-
	ISOLATED OF (EV).		150.00	150.00
			6,058.00	1,290.00
	GRAND TOTAL		15,780.19	2,281.31





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		2,281.31
(CONFIRMED)		

Report Ref No. NS/INC22004335/Rvcn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser